

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27536

Release Notification and Corrective Action

nMLB/123850893

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name Poker Lake Unit #78 Delaware B Tank Battery		Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No.
-----------------------	-----------------------	-----------


LOCATION OF RELEASE

Unit Letter A	Section 25	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.194069 Longitude W 103.827614

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 40 Bbls of crude oil.	Volume Recovered: 30 bbls.
Source of Release: 500 bbl oil production tank.	Date and Hour of Occurrence 8/20/11 time unknown.	Date and Hour of Discovery 8/20/11 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 Randy Dade	
By Whom? Tony Savoie	Date and Hour 8/20/11 11:07 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		



Describe Cause of Problem and Remedial Action Taken.* One of the oil production tanks overflowed. Cause unknown.

Describe Area Affected and Cleanup Action Taken.*The spill was contained within the earthen containment around the tank battery, all of the free product was removed with a vacuum truck.

The Site remediation for the produced water and crude oil spill will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by District Supervisor: Signed By: [Signature]	
Title: Waste Mgmt. & Remediation Specialist		Approval Date: AUG 26 2011	Expiration Date:
E-mail Address: TASavoie@BassPet.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/22/11 Phone: 432-556-8730		Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

9/26/2011

2RP-870