



Inspections:				
Inspection Type	Vehicle	Driver	Hazmat	IEP
Inspections	4	4	0	0
Out of Service	1	0	0	0
Out of Service %	25%	0%	%	0%
Nat'l Average % as of DATE 12/29/2023*	22.26%	6.67%	4.44%	N/A

\*OOS rates calculated based on the most recent 24 months of inspection data per the latest monthly SAFER Snapshot.

Crashes reported to FMCSA by states for 24 months prior to: 01/18/2024

**Note:** Crashes listed represent a motor carrier’s involvement in reportable crashes, without any determination as to responsibility.

Crashes:				
Type	Fatal	Injury	Tow	Total
Crashes	0	0	0	0

[ID/Operations](#) | [Inspections/Crashes In US](#) | [Inspections/Crashes In Canada](#) | [Safety Rating](#)

Canadian Inspection results for 24 months prior to: 01/18/2024

Total inspections: 0

**Note:** Total inspections may be less than the sum of vehicle and driver inspections. Go to [Inspections Help](#) for further information.

Inspections:		
Inspection Type	Vehicle	Driver
Inspections	0	0
Out of Service	0	0
Out of Service %	0%	0%

Crashes results for 24 months prior to: 01/18/2024

**Note:** Crashes listed represent a motor carrier’s involvement in reportable crashes, without any determination as to responsibility.

Crashes:				
Type	Fatal	Injury	Tow	Total
Crashes	0	0	0	0

[ID/Operations](#) | [Inspections/Crashes In US](#) | [Inspections/Crashes In Canada](#) | [Safety Rating](#)

The Federal safety rating does not necessarily reflect the safety of the carrier when operating in intrastate commerce.

Carrier Safety Rating:

The rating below is current as of: 01/18/2024

Review Information:

Rating Date:	None	Review Date:	None
Rating:	None	Type:	None

HOME

Company Summary

Cases List

Company Rules

Docs List

DBA History

Certification

Authority

Insurance Hist.

Inspection Fees

Fees

Notes

Company Information

Industry Type TRANSPORTATION	Industry Sub Type <u>GENERAL COMMODITIES/PROPERTY</u>	Ownership Type LLC
Certification Status <u>CERTIFIED</u>	Current Address? YES	Master Name Current? <u>YES</u>
Company Name	HERRERA'S OILFIELD SERVICES, LLC	
Address (Street 1st Line) / Mailing	PO BOX 96	
Street (2nd Line)		
City EUNICE	State NM	Zip 88231-0000
County LEA	Phone # 575-394-0492	Company Code
Equipment Storage Location 27 South New Mexico HWY 207, Eunice, NM 88231		
Records Location		
Station Points		

Owner Information

Owner Name	CARLOS HERRERA	
Address (Street 1st Line) / Physical	27 SOUTH NEW MEXICO HWY 207	
Street (2nd Line)		
City EUNICE	State NM	Zip 88231-0000
Phone # 575-394-0492	Email ADMIN@HERRERASOILFIELD.COM	

Agent / Attorney Information

Agent (Attorney) Name	Nellie Herrera		
Agent (Attorney) Name (2nd)			
Address (Street 1st Line)	1006 AVE G		
Street (2nd Line)			
City Eunice	State NM	Zip 88231-0000	
Phone # 575-942-0323	Email NELLIEGARZA81@GMAIL.COM	Last Update 11/27/2023	Updated By GARCIA, JUSTIN

Company's Current Case List (10 records)

Case #	Case Company Name (Address)	Case Type	File Date	Type	Case Status	Disposition
<u>23-00385-TRM</u>	HERRERA'S OILFIELD SERVICES, LLC (PO BOX 96, EUNICE NM 88231-0000)	TRANSPORTATION	11/27/2023	PRIMARY	CLOSED	

Tips: Click Update button to update record or Delete button to delete record.

Copyright © CSI Technology Group. All rights reserved.

U.S. DOT# 3073828 has no current for-hire operating authority with FMCSA.

### Learn About the CSA Prioritization Preview

FMCSA is proposing a new prioritization methodology to keep enforcement efforts focused on the carriers in most need of intervention. Learn more about these changes and how they will improve highway safety.

[Visit the CSA Prioritization Preview](#)

**HERRERAS OILFIELD SERVICES LLC**

U.S. DOT#: 3073828  
Number of Vehicles: 1  
Number of Drivers: 1  
Number of Inspections: 4

**Safety Rating & OOS Rates**

(As of 01/18/2024 updated daily from [SAFER](#))

Not Rated

**Out of Service Rates**

Type	OOS %	National Avg %
Vehicle	25.0	21.4
Driver	0.0	6.0
Hazmat		4.5

**Licensing and Insurance**

(As of 01/18/2024 updated hourly from [L&I](#))

Active For-Hire Authority		
Type	Yes/No	MC#/MX#
Property	No	
Passenger	No	
Household Goods	No	
Broker	No	

**BASIC Status** (Public Property Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICS)

[View CSA Prioritization Preview](#) →  
Based on a 24-month record ending December 29, 2023

Unsafe Driving	Not Public Crash Indicator	Hours-of-Service Compliance	Vehicle Maintenance	Controlled Substances and Alcohol	Not Public Hazardous Materials Compliance	Driver Fitness

**On-Road Performance**

0 Measure	NOT PUBLIC	0 Measure	9.25 Measure	0 Measure	NOT PUBLIC	0.50 Measure
--------------	---------------	--------------	-----------------	--------------	---------------	-----------------

**On-Road Performance Detail**


Driver Inspections with Unsafe Driving Violations: 0	NOT PUBLIC	Driver Inspections: 4 with HOS Compliance Violations: 0	Vehicle Inspections: 4 with Vehicle Maint. Violations: 3	Driver Inspections: 4 with Drugs/Alcohol Violations: 0	NOT PUBLIC	Driver Inspections: 4 with Driver Fitness Violations: 2
Safety Event Group: No Safety Event Grouping		Safety Event Group: 3-10 relevant driver inspections	Safety Event Group: No Safety Event Grouping	Safety Event Group: No Safety Event Grouping		Safety Event Group: No Safety Event Grouping
Avg. PU × UF: 2.5						
Segment: Straight Carrier						


Investigation Results						
No Acute/Critical Violations Discovered	N/A	No Acute/Critical Violations Discovered	No Acute/Critical Violations Discovered	No Acute/Critical Violations Discovered	NOT PUBLIC	No Acute/Critical Violations Discovered

Select a BASIC icon above to get details, or view your [Complete SMS Profile](#).

<h3>Summary of Activities</h3> <p>The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.</p> <p>Most Recent Investigation: Total Inspections: 4     Total Inspections without Violations used in SMS: 1     Total Inspections with Violations used in SMS: 3 Total Crashes* : 0</p> <p>*Crashes listed represent a motor carrier’s involvement in <a href="#">reportable crashes</a>, regardless of the carrier’s or driver’s role in the crash. <a href="#">Continue for details</a>.</p>	<h3>Carrier Registration</h3> <p>Subject to General Threshold</p>	<h3>Enforcement Cases</h3> <p>(Six years as of 01/18/2024 updated monthly from <a href="#">FMCSA</a>)</p> <p>No penalties found</p>
--	---	---

USE OF SMS DATA/INFORMATION

<p><b>FAST Act of 2015:</b></p> <p>Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.</p> <p><b>Safety Measurement System:</b></p> <p>The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A  symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.</p>
---

The  symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at <http://safer.fmcsa.dot.gov> and motor carrier licensing and insurance status are available at <http://li-public.fmcsa.dot.gov/>.

[HOME](#)

## Search Information

[Home](#)

### Entity Details

Business ID#: **5487480**Status: **Active**Entity Name: **Herrera's Oilfield Services, LLC**Standing: **Good Standing**DBA Name: **Not Applicable**

### Entity Type and State of Domicile

Entity Type: **Domestic Limited Liability Company**State of Incorporation: **New Mexico**Statute Law Code: **53-19-1 to 53-19-74**

### Formation Dates



### Reporting Information



### Period of Existence and Purpose and Character of Affairs



### Outstanding Items

Not Applicable

### Registered Agent:

No Records Found.

### License:

No Records Found.

### Contact Information

Mailing Address:

Principal Place of Business  
Anywhere: **27 South New Mexico Highway 207, Eunice, NM 88231**Secondary Principal Place of  
Business Anywhere:Principal Office Outside of New  
Mexico: **Not Applicable**Registered Office in State of  
Incorporation:

Principal Place of Business in  
Domestic State/ Country: **Not Applicable**

Principal Office Location in NM: **Not Applicable**

### Registered Agent Information

Name: **Carlos Herrera**

Geographical Location  
Address:

Physical Address: **27 South New Mexico  
Highway 207, Eunice, NM  
88231**

Mailing Address: **NONE**

Date of Appointment: **07/13/2017**

Effective Date of Resignation:

### Director Information

**Not Applicable**

### Officer Information

**Not Applicable**

### Manager Information

No Records to View.

### Member Information

No Records to View.

### Organizer Information

Title	Name	Address
Organizer	Carlos Herrera	27 South New Mexico Highway 207, Eunice, NM 88231

### Incorporator Information

**Not Applicable**

### Trustee Information

**Not Applicable**



## Filing History



## License History

[Back](#)[Entity Name History](#)[Return to Search](#)