

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
811 S First St, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NMLB/125149183*

<b>OPERATOR</b>		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company <i>George A. Chase jr 265378</i>	Contact <i>George Chase jr</i>		
Address <i>P.O. Box 1618 Artesia, NM 88211-1618</i>	Telephone No. <i>575-365-8702</i>		
Facility Name <i>Rutter fed # 3</i>	Facility Type <i>Gas well</i>		
Surface Owner <i>Private</i>	Mineral Owner <i>G&amp;C Service</i>	API No. <i>30-015-24530</i>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>H</i>	<i>22</i>	<i>16S</i>	<i>31E</i>	<i>1650</i>	<i>North</i>	<i>990</i>	<i>East</i>	<i>Eddy</i>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release <i>Produced water</i>	Volume of Release <i>3 bbls</i>	Volume Recovered <i>0 bbl</i>
Source of Release	Date and Hour of Occurrence <i>NA</i>	Date and Hour of Discovery <i>06/15</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**  
SEP 15 2011  
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* *Nipple on water tank rotted and leaked 3 barrels of produced water. Tank has been removed. Containment berm was installed.*

Describe Area Affected and Cleanup Action Taken.\* *Leak occurred on location in a 5x10' area. Backhoe removed contaminated soil and replaced it with Coliache.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>George A. Chase jr</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>George Chase jr.</i>	Signed By <i>Mike Beaman</i>	
Title: <i>Owner</i>	Approved by Environmental Specialist:	Approval Date: <i>SEP 20 2011</i> Expiration Date: <i>NA</i>
E-mail Address: <i>3jchase@myway.com</i>	Conditions of Approval: <i>NA</i>	Attached <input type="checkbox"/>
Date: <i>09/15/2011</i> Phone: <i>365-8702</i>	<i>Final</i>	

\* Attach Additional Sheets If Necessary

*2RP-874*