


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB/125156113

129/37

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Randall Federal #3	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-38389

LOCATION OF RELEASE

Unit Letter P	Section 7	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 50.565 Longitude 104 00.327

NATURE OF RELEASE

Type of Release Oil	Volume of Release 23bbls	Volume Recovered 22bbls
Source of Release Oil tank	Date and Hour of Occurrence 08/06/2011	Date and Hour of Discovery 08/06/2011 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The release was caused by trucks not arriving on time to haul off oil from the tanks.		
Describe Area Affected and Cleanup Action Taken.* Initially 23bbls were released from the oil tank and we were able to recover 22bbls with a vacuum truck. The entire release was completely contained inside the dike walls of the tank battery. This tank battery is lined with 40mil plastic. All standing fluid has been picked up. Any stained gravel has been removed and fresh gravel has been added as necessary. The tank battery has been returned to its prior location.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Signed By Approved by District Supervisor:	
Title: HSE Coordinator	Approval Date: SEP 08 2011	Expiration Date: N/A
E-mail Address: jrusso@conchoresources.com	Conditions of Approval: N/A 	Attached <input type="checkbox"/>
Date: 08/22/2011 Phone: 432-212-2399		

* Attach Additional Sheets If Necessary

2RP-878

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Tuesday, August 23, 2011 2:43 PM
To: Bratcher, Mike, EMNRD; 'james_amos@nm.blm.gov'
Subject: C-141 - Randall Federal #3 Tank Battery
Attachments: RANDALL FEDERAL #3 -- DATE OF RELEASE -- 08-06-2011.pdf

Gentlemen,

Please see attached the C-141 Initial/Final Report for a release that occurred at the Randall Federal #3 Tank Battery on 08/06/2011. This release occurred inside a lined facility.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.