

3R - 427

C-144

02/22/2007

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	EL PASO	Facility Type	Gas Well
	1A	API #	3004522778
Surface Owner	Mineral Owner	Federal	Lease No.
			NMNM-0560422

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	20	029N	009W	500	North	1840	West	San Juan
Latitude					Longitude			

NATURE OF RELEASE

Type of Release	No Release - Impacted Soils - Possible GW	Volume of Release	0 BBLS	Volume Recovered	0 BBLS
Source of Release	No Release - Impacted Soils Discovered	Date and Hour of Occurrence	2/22/2007	Date and Hour of Discovery	2/22/2007
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Glen Von Gonten		
By Whom?	Ed Hasely	Date and Hour	2/23/2007 10:30:00 A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

During the trenching for a new flowline, hydrocarbon impacted soils were discovered. Upon excavation of the impacted soils, water seeped into the excavation.

Describe Area Affected and Cleanup Action Taken.*

Impacted soils were excavated to an approximate size of 30' x 45' x 9' deep. A soil sample from the SW corner of the excavation was collected (attached). Another composite sample was collected from the 4 walls and will be submitted to the OCD when available. The soils were hauled to commercial disposal. The excavation was backfilled w/ clean soils. A water sample will be collected and the results will be submitted to the OCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name:	Monica D. Johnson	Approved by District Supervisor:	
Title:	Environmental Specialist	Approval Date:	Expiration Date:
E-mail Address:	monica.johnson@conocoPhillips.com	Conditions of Approval:	Attached
Date:	Phone: (505) 326-9829		<input type="checkbox"/>

* Attach Additional Sheets If Necessary