District I 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Biazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr , Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Santa Fe, NM 87505

NOV **3** 2011

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr.

NMOCD ARTES Leave with 19 15 29 NMAC

Release Notification and Corrective Action				
nMLB//3//3//98	<b>OPERATOR</b>		Final Report	
Name of Company Linn Operating 269324	Contact Joe Hernandez			
Address 2130 W Bender Hobbs, NM 88240	Telephone No · 575-738-1739			
Facility Name Puscell Turner WaterFlood	English Type Water Flood			

Surface Owner. BLM Mineral Owner BLM API No.. 30-015-20109 TURNER B 79 LOCATION OF RELEASE Unit Letter Feet from the East/West Line Section Township Range Feet from the North/South Line County 20 17S 2050 31E S 1980 W K Eddy

<b>Latitude:</b> 32° 49′ 6.0″ <b>Longitude:</b> -103° 53′ 38 3″				
NATURE OF RELEASE				
	Volume of Release 60	Volume Recovered 30		
Source of Release Produced water In Cine	Date and Hour of Occurrence 10/25/2011 7 30am	Date and Hour of Discovery 10/25/2011 8 00am		
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required	If YES, To Whom? Terry Gregston -NM BLM	Notification to NONCO		
By Whom <sup>9</sup> Joe Hernandez	Date and Hour 10/25/2011			
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse			
If a Watercourse was Impacted, Describe Fully *				
Describe Cause of Problem and Remedial Action Taken.* A section of the 3" steel injection line had been replaced sometime in the past. The pipe was used to fix the leak at that time, it was not coated like the original steel line and weekend over time and finally gave way to the high line pressure -Steel pipeline/ corrosion				
Describe Area Affected and Cleanup Action Taken * Hungy Horse dug up around the line to expose leak and put dirt on plastic Waiting to hear from BLM to finish cleanup				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Signature	OIL CONSERVATION DIVISION Approved by Figure Riperfusor Landson			
Printed Name Joe Hernandez		1 - Traville Com		
Title Production Foreman	Approval Date NOV 0 7 2011	Expiration Date		
E-mail Address jhernandez@linnenergy com  Date 11/02/2011 Phone 575-942-9492	Conditions of Approval Remediation per OCD Rules	& Attached		
Att 1 Additional Charte ICN annual		ON - 4 (-		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL, NOT LATER THAN:

2RP-948

## Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]

Sent: Thursday, November 03, 2011 8.42 AM

To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)

Cc: Daniel Frick

Subject: Linn- Russell Turner WaterFlood C-141 Initial

Attachments: Russell Turner Waterflood C-141 Initial 11-02-11.pdf

Please see attached C-141 for above referenced location.

Thank you,

## Theresa McCracken

## **LINN Operating**

2130 W. Bender Blvd Hobbs, NM 88240 (575)738-1739

tmccracken@linnenergy.com