


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 3 copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nMLB/10341-55127

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Skelly 989 Tank Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No.	NMNM-029418A (API#) 30-015-36498

LOCATION OF RELEASE

Unit Letter F	Section 23	Township 17S	Range 31E	Feet from the 1980	North/South Line North	Feet from the 1649	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32 49.316 Longitude 103 50.617

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	24bbls	Volume Recovered	23bbls
Source of Release	Oil tank	Date and Hour of Occurrence	11/13/2010	Date and Hour of Discovery	11/13/2010 8:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The float inside the oil tank blocked the equalizer line causing the tank to overflow. The float has been inspected and the tank has been returned to service.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 24bbls of oil was released from the tank and we were able to recover 23bbls with a vacuum truck. All fluid was contained inside the facility firewall, which is lined with a 40 mil plastic liner. The contaminated gravel has been removed and we replaced with clean gravel as necessary. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Approved by District Supervisor:			
Title: HSE Coordinator		Approval Date: NOV 15 2011		Expiration Date: NA	
E-mail Address: jrusso@conchoresources.com		Conditions of Approval: NA		Attached <input type="checkbox"/>	
Date: 11/14/2011 Phone: 432-212-2399					

* Attach Additional Sheets If Necessary

2CP-494

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Monday, November 14, 2011 2:41 PM
To: Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: Gregston, Terry G
Subject: C-141 Final Report - Skelly 989 TB
Attachments: img-Y14163458-0001.pdf

Please see attached the C-141 Final Report for a release that occurred last year on 11/13/2010. My records did not indicate that I had sent a Final Report for this specific release and I wanted to be sure that you had one for your files.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.