

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Targa Midstream Services, L.P.	Contact: Ralph England
Address: P.O. Box 1689	Telephone No.: 575.441.4653
Facility Name: Saunders Plant	Facility Type: 16" steel pipeline

Surface Owner: State Of New Mexico	Mineral Owner:	Lease No.: N/A
------------------------------------	----------------	----------------

LOCATION OF RELEASE

NEARBY WELL

MAUD SAUNDERS 004-API# 30-025-01195

Unit Letter F	Section 20	Township 15S	Range 34E	Feet from the 1678'	North/South Line NORTH	Feet from the 1784'	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	---------------

Latitude 33.00496 Longitude 103.53598

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release Unknown	Volume Recovered None
Source of Release 16" Steel Pipeline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 8/1/2011, 2:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Liking	
By Whom? Ralph England	Date and Hour 10:26 Am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

6 pin hole sized leaks in 16" Steel Low Pressure Gathering Line located in section 20 T15S R34E. Leaks have been repaired by repair clamps until a new section of pipe can be purchased and installed.

Describe Area Affected and Cleanup Action Taken.*

Remove contaminated soil and replace with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ralph England</i>		OIL CONSERVATION DIVISION	
Printed Name: Ralph England		ENV SPECIALIST: Approved by District Supervisor: <i>Geoffrey Liking</i>	
Title: Field Supervisor		Approval Date: 12/07/11	Expiration Date: 02/07/12
E-mail Address: rengland@targaresources.com		Conditions of Approval: SUBMIT FINAL C-141 BY 02/07/12.	
Date: 8-1-11	Phone: (575) 441-4653	Attached <input type="checkbox"/> IRP-12-11-2767	

* Attach Additional Sheets If Necessary

DEC 08 2011