

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chaparral Energy Co. LLC	Contact: Derek E. Presley
Address: 701 Cedar Lake Blvd. Oklahoma City, OK 73114	Telephone No.: (405) 426-4091 X 1491
Facility Name: WDQSU #96	Facility Type: Oil Well active

Surface Owner: Willis Family Estate	Mineral Owner: Federal	Lease No.:
-------------------------------------	------------------------	------------

LOCATION OF RELEASE API # 30-025-30166-00-00

Unit Letter C	Section 31	Township 24S	Range 38E	Feet from the 990	North/South Line NORTH	Feet from the 1700'	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	----------------------	---------------------------	------------------------	------------------------	---------------

Latitude: 32.1783468827639

Longitude: 103.102621289441

NATURE OF RELEASE

Type of Release: Produce water and oil	Volume of Release: 7bbls	Volume Recovered: 0bbls
Source of Release: well casing surface valve corroded	Date and Hour of Occurrence: 11-29-11	Date and Hour of Discovery: 12:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES. To Whom?	
By Whom? OCD will be notified when C-141 is turned in. volume of release requires notification within 14 days	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES. Volume Impacting the Watercourse.	

If a Watercourse was impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

surface casing connection at 90° corroded allowing water to flow out. Connections replaced with new piping, valve and pressure gauge (zero reading on gauge). Leak area back dragged using backhoe to prevent livestock from drinking water.

Describe Area Affected and Cleanup Action Taken.*

Affected area remained on location with approx. 1845sqft. WEE / ET of NM has been contracted to delineate the spill site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	ENV SPECIALIST: Approved by District Supervisor: <i>Jeffrey Beling</i>	
Printed Name: Derek E. Presley	Approval Date: 12/07/11	Expiration Date: 02/07/12
Title: Safety Specialist	Conditions of Approval: SUBMIT FINAL C-141 BY 02/07/12.	
E-mail Address: derek.presley@chaparralenergy.com	Attached <input type="checkbox"/>	IRP-12-11-2708
Date: 12/5/11	Phone: (405) 426-4091 X 1491	

* Attach Additional Sheets if Necessary

DEC 08 2011