

- TARGA'S ONSITE INJECTION WELL
- MONITOR WELL LOCATION (DEEP)
- RECOVERY WELL LOCATION

OFFSITE PROPERTY WELLS "NOT SAMPLED"

CHLORIDE INVESTIGATION AREA

SCALE VERIFICATION

Chevron Environmental **Management Company** 

EUNICE SOUTH

SITE DETAILS MAP **EUNICE, NEW MEXICO** 



CONESTOQA-ROVERS & ASSOCIATE

USGS 1988 AERIAL TLARSON 055271-09

002