


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

NMLB 1135451995

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739
Facility Name: Max Friess #2		Facility Type: Water Injection

Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001505469
--------------------	--------------------	---------------------

LOCATION OF RELEASE

Unit Letter A	Section 30	Township 17S	Range 31E	Feet from the 660	North/South Line N	Feet from the 660	East/West Line N	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-----------------------	----------------------	---------------------	----------------

Latitude: 32° 48' 46.5" Longitude: -103° 54' 13.7"

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 40	Volume Recovered: 35
Source of Release: Pipeline -Steel	Date and Hour of Occurrence: 12/13/2011 9:00am	Date and Hour of Discovery: 12/13/2011 9:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD / Terry Gregston - BLM	
By Whom? Joe Hernandez	Date and Hour 12/13/2011 2pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: 4" trunk line, seam on pipe opened about an 1" due to corrosion. Water surfaced ran southwest 420ft narrowest spot 1ft wide by 225ft widest point by 15ft

Describe Area Affected and Cleanup Action Taken.*: dug up source of the leak, 12-14-11 kenemore patched line, clean up to start at later date.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

OIL CONSERVATION DIVISION

Signature: <i>[Signature]</i>	SIGNED BY <i>[Signature]</i>	
Printed Name: Joe Hernandez	Approved by District Supervisor:	
Title: Production Foreman	Approval Date: DEC 20 2011	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval	Attached <input type="checkbox"/>
Date: 12/19/2011 Phone: 575-942-9492	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

1/20/2012

2RP-983

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Monday, December 19, 2011 9:08 AM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- Max Friess # 2 Initial C-141

Please find attached the initial C-141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@linnenergy.com