


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised March 17, 1999
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-20001

Release Notification and Corrective Action

NMLB 1201931042

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211		Telephone No. 575-748-5238
Facility Name Littlefield AB #5		Facility Type Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter <i>M</i>	Section 22	Township 18S	Range 31E	Feet from the 660	North/South Line South	Feet from the 660	East/West Line West	County Lea County <i>EDDY</i>
-------------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	--

NATURE OF RELEASE

Type of Release Produced Water & Oil	Volume of Release 3 Oil/7 Water	Volume Recovered 3 bbls. Oil
Source of Release Flow Line Union	Date and Hour of Occurrence 12/9/11, 10:18 AM	Date and Hour of Discovery 12/9/11, 10:18 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD (Jeff Lekin) BLM (Trish Badbear)	
By Whom?	Date and Hour NMOCD 12/9/11, 12:35 PM; BLM 12/9/11, 12:40 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Union was loosened due to recent freeze, while thawing it caused the leak. Called Vacuum Truck and Tightened Union, Mike Stubblefield with Talon will take samples for proper clean up.

Describe Area Affected and Cleanup Action Taken.*

Area affected was 15' x 20', Sandy Open Pasture Land

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature: <i>Gracie Bustamante</i>	Approved by District Supervisor		
Printed Name: Gracie Bustamante	Signed By: <i>[Signature]</i>		
Title: Field Tech (Contract)	Approval Date: <i>1/18/2012</i>	Expiration Date:	
Date: 12-12-11 Phone: (575) 746-5554	Conditions of Approval:		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
Proposal Rec'd 1/13/12

2RA-988