


District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

### Release Notification and Corrective Action

NMLB/203249519

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739
Facility Name: Fren Oil #5		Facility Type: Water Flood
Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001505253

### LOCATION OF RELEASE

Unit Letter P	Section 19	Township 17S	Range 31E	Feet from the 660	North/South Line S	Feet from the 660	East/West Line E	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-----------------------	----------------------	---------------------	----------------

Latitude: 32° 48' 52.2" Longitude: -103° 54' 9.7"

### NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 3 / 16	Volume Recovered: 1 / 12
Source of Release: Pipeline	Date and Hour of Occurrence: 12/15/2011 9:32am	Date and Hour of Discovery: 12/15/2011 10:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD	
By Whom? Joe Hernandez	Date and Hour 12/16/2011 9am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Received call from roustabout crew that there was a leak on the water line. Seam split open 1 1/2 " wide, due to corrosion.		
Describe Area Affected and Cleanup Action Taken.* : Vacuum truck picked up any fluid off ground, back hoe dug line out where leak was Kenemore will patch line.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By <u>Mike Bratcher</u>	
Title: Production Foreman	Approved by District Supervisor:	
E-mail Address: jhernandez@linenergy.com	Approval Date: FEB 01 2012	Expiration Date:
Date: 12/27/2011 Phone: 575-942-9492	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

3/1/2012

2RP-990

## Bratcher, Mike, EMNRD

---

**From:** Theresa McCracken [TMcCracken@linnenergy.com]  
**Sent:** Tuesday, December 27, 2011 8:30 AM  
**To:** Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)  
**Cc:** Daniel Frick  
**Subject:** Linn- Fren Oil #5 Initial C-141  
**Attachments:** Fren Oil #5.pdf

Please find attached the Initial C-141 for the above reference location.

Thank you,

*Theresa McCracken*

**LINN Operating**  
2130 W. Bender Blvd  
Hobbs, NM 88240  
(575)738-1739  
[tmccracken@linnenergy.com](mailto:tmccracken@linnenergy.com)