District I 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Biazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

FEB **0 1** 2012

RECEIVED

Form C-141 Revised October 10, 2003

NMOCD AF accordance with 19.15.29 NMAC

Oil Conservation Division
1220 South St. Francis Dr.

Santa Fe, NM 87505

Release Notification and Corrective Action												
Name of Company: Linn Operating 269324										ıl Report		Final Report
		nn Operating		Contact: Joe Hernandez								
		der Hobbs, A Battery-			Telephone No.: 575-738-1739 Facility Type: WaterFlood							
		A ballery-										
Surface Ow	ner: BLM		Mineral O	wner: E	r: BLM API No.: 3001528758							
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County												
Unit Letter I	Section 19	Township 17S	Range 31E	Feet from the 2632		South Line North	Feet from the 75		Zest Line East	County	Eddy	
Latitude: N32° 49' 16.2" Longitude: W103° 44' 48.2"												
NATURE OF RELEASE												
Type of Rele			Volume of Release: 100 Volume Recovered: 70									
Source of Re	lease: Pipeli		Date and Hour of Occurrence:  Date and Hour of Discovery:						:			
Was Immedia	ate Notice C		01/24/2012 9:00am 01/24/2012 9:30am If YES, To Whom?									
•		quired										
By Whom? J			Date and Hour 01/24/2012 3:00pm									
Was a Water	course Reac	hed?		If YES, Volume Impacting the Watercourse.								
If a Watercourse was Impacted, Describe Fully.*:												
,												
Describe Cause of Problem and Remedial Action Taken *: Bolts on clamp rotted. Transfer pump was running and caused water to leak and run down lease road south about 100 yards. Shut down leases and replaced with new piece of pipe and two clamps on both sides. Next day pressure up and no leaks.												
Describe Area Affected and Cleanup Action Taken.*: Loco Hills East on 82 to mile marker 137, turn north .3miles leak on west side of lease road. Sucked up water.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
	- J 🦴	4		OIL CONSERVATION DIVISION								
Signature:	d.,h/d <b>/3</b> 00 f.y.,	kas is a religious of			Approved by District Supervisor:							
Printed Name: Joe Hernandez												
Title: Produc	tion Forema	ın		Approval Date: Expiration Date:								
E-mail Addre	ail Address. Jhernandez@linnenergy.com		(	Conditions of Approval: Remediation per OCD Rules &				Attached				
Attach Addi				<u> </u>	امانت	lines. SUB OSAL NOT	MIT REMEDIA LATER THAN	411014	6	2 <i>FP</i> -	10	15

## Bratcher, Mike, EMNRD

Theresa McCracken [TMcCracken@linnenergy.com] From:

Sent:

Wednesday, February 01, 2012 8:36 AM
Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov) To:

Cc: Daniel Frick

Linn- Initial C-141 Turner A Battery-Turner A #51 Subject:

Turner A Battery-Turner A #51.pdf Attachments:

Please find attached the Initial C-141 for the above referenced location.

Theresa McCracken LINN Operating 2130 W. Bender Blvd Hobbs, NM 88240 (575)738-1739 tmccracken@linnenergy.com