<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District III

1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

Form C-141 Revised August 8, 2011

FEB 0 7 2012

Submit 1 Copy to appropriate District Office in NMOCD ARTESIA

Revised August 8, 2011

Release Notification and Corrective Action

nMLB1204646257 20989					7	OPERA'	OR		Initia	ıl Report	Final Repo	ort	
Name of Company SMITH + MARS						Contact	DALT	04	BBI	4			
Address BOX 863 K R.R.M. (TTX 74745) Telephone No. 575 748 2134													
Facility Name ADKINS WILLIAMS LS. Facility Type THUK BATTERY													
Surface Ow	ner 🙏	(PW MIN	AKIC O	Mineral O	wner	er N. M. API No. 30-015-01920-0						<u></u>	
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	est Line	County			
O	17	185	286	890	5	0UTH	2310	EA	5T	R DD)	/		
	***************************************		Lat	itude		Longitud	e				. 6 0		
NATURE OF RELEASE													
Type of Release B. S OIL - WATEN Volume of Release - 5 BBL Volume Recovered - 5 BBLS													
Source of Release TAUK BOTTOM Date and Hour of Occurrence 2-6-1/2 Date and Hour of Discovery 2-6-12													
Was Immedia	ate Notice (Given?			If YES, To Whom?								
		₩	Yes 📙	No Not Re	quired	1 501 1019331405, 1110160114							
By Whom? りんしゃりん Bなしし Was a Watercourse Reached?							Date and Hour $2 - 6 - 12$ $7 PM$						
Was a Water	course Read	If YES, Volume Impacting the Watercourse.											
If a Watercox	urse was Im	pacted, Descri	he Fully *	<u> </u>		<u> </u>						_	
I a watereet	405 H	pacted, Besch	oo r uny.				-						
Describe Course of Development of Demodial Action Token *													
Describe Cause of Problem and Remedial Action Taken.*													
TANK TO BE CHEANED - TRUCK ON LOCATION													
PICKED UP MOST OF SPILL													
Describe Are	a Anecteu	and Cleanup A	scion rak	1 h c.A.T (8	16	& ROA	$_{D}$ W	124	KB,	MAIRI	ANK.		
[•	LUCHIL	1-1	A 100 11		1.1	هدر	120 BK	ŀ		
Describe Area Affected and Cleanup Action Taken.* LOCATION FROND WILL REPAIR TANK AN CREAN UP AREA													
71 1	C 41 41							•					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
federal, state	, or local la	ws and/or regu	lations.				OIT CON	TOTON	ATTONI	DÍVICIO			
ļ		n &	//,		- 1		OIL CON	NSER V	AHON	DÍVISIO	<u>. Y</u>		
Signature:			$\mathcal{V}_{\mathcal{U}}$	J)					/ ,				
						Approved by Entrophen Bil Specialist: Describe							
Printed Nam	e: <i>D (</i>	A LTON	131	ELL									
Title:	61	- BRK				Approval Date: B 1 5 2012 Expiration Date:							
E-mail Addr	ess:		i			Conditions o	f Approval:			Attached	П		
	9 9			440 2 121		namadiati	on ner OCD R	ules &	_	Audolou			
Date:		- 12 - 1501		748-2134	Guid	telines. SU	BMIT REMEL	MAHON	·	1			
Date: 2-7-12 Phone: 748-2134 *Attach Additional Sheets If Necessary PROPOSAL NOT LATER THAN: PROPOSAL NOT LATER THAN: PROPOSAL NOT LATER THAN:													
					PKC	1/	15/2012		1	-1-1	way		