District I 1625 N. Frenci	RECEIVED
District II 1301 W Gran	d Avenuer Antesia, 3NM 88210
1000 Rio Braz	- D 1 A- ( ) NA 87410
District IV 1220 S. St. Fra	NM Salec, NM 87410 SIA

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

# **Release Notification and Corrective Action**

MLB/204742414	OPER	ATOR	Initial Report	Final Report
Name of Company	OGRID Number	Contact		
Yates Petroleum Corporation	25575	Robert Asher		
Address		Telephone No.		
104 S. 4 <sup>TH</sup> Street		575-748-1471		
Facility Name	API Number	Facility Type		
Luminary BAU Federal Com. #2	30-005-63567	Battery		
Surface Owner	Mineral Owner		Lease No.	
Federal	Federal		NM-111037	

## LOCATION OF RELEASE

				_ +				
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	115	26E	990	North	990	East	Chaves

Latitude 32.32589 Longitude 104.30513

#### NATURE OF RELEASE Type of Release Volume of Release Volume Recovered 50 B/O Oil 35 B/O Source of Release Date and Hour of Occurrence Date and Hour of Discovery Production Line 1/28/2012 - AM 1/28/2012 - AM Was Immediate Notice Given? If YES, To Whom? Yes No Not Required Mike Bratcher/NMOCD II By Whom? Date and Hour Robert Asher/Yates Petroleum Corporation 2/6/2012, PM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. N/A 🗌 Yes 🛛 No If a Watercourse was Impacted, Describe Fully.\* N/A Describe Cause of Problem and Remedial Action Taken.\* Trash or paraffin in line caused water to go into oil tank to fill up and overflow oil on ground. Vacuum truck and backhoe crew called. Describe Area Affected and Cleanup Action Taken.\* An approximate area of 50' x 40' inside battery. Remaining oil picked up by vacuum truck inside the battery. Impacted soils were excavated and hauled to an NMOCD approved facility. Initial vertical and horizontal delineation samples with in the impacted area will be taken and analysis ran for TPH & BTEX. If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL, a work plan will be submitted to the OCD. Depth to Ground Water: >100' (approximately 166', T11S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION 0 Signature: Approved by District Supervise Printed Name: Robert Asher Approval Date: EB 1 6 2012 Title: Senior Environmental Regulatory Agent **Expiration Date:** E-mail Address: boba@yatespetroleum.com Conditions of Approval: Remediation per OCD Rules & Attached TION Date: Monday, February 13, 2012 Phone: 575-748-4217 2RP-1029

\* Attach Additional Sheets If Necessary

Guidelines. SUBMIT REMEDIA
PROPOSAL NOT LATER THAN:
2/16/2012

## Bratcher, Mike, EMNRD

From: Sent:	Bob Asher [BobA@yatespetroleum.com] Monday, February 06, 2012 3:41 PM
То:	Bratcher, Mike, EMNRD; Dade, Randy, EMNRD
Cc:	Amanda Trujillo; Amber Cannon; Jeremy Haass; Jerry Fanning; Lisa Norton
Subject:	Release: Luminary BAU Federal com. #2

Yates Petroleum Corporation is reporting a release at the following location.

Luminary BAU Federal Com. #2 30-005-63567 Section 35, T11S-R26E Chaves County, New Mexico

Released: 50 B/O; Recovered: 35 B/O

Trash or paraffin in flow line caused water to go into oil tank and overflow oil out of tank. I was not notified of release until today, which occurred on 1/28/2012; please contact me if there are any questions.

A Form C-141 Initial Report will be submitted with complete information.

Thank you.

## **Robert Asher**

Senior Environmental Regulatory Agent Yates Petroleum Corporation 105 S. Fourth Street Artesia, NM 88210 575-748-4217 (Direct) 575-365-4021 (Cell)