

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

NM 11/10/56 737

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Koonunga Hill BGX Federal #1	API Number 30-015-34380	Facility Type Gas well
		Order Number 2RP- 734

Surface Owner Federal	Mineral Owner Federal	Lease No. NM - 103594
--------------------------	--------------------------	--------------------------

LOCATION OF RELEASE

Unit Letter E	Section 19	Township 22S	Range 25E	Feet from the 1838	North/South Line NORTH	Feet from the 1072	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release WATER	Volume of Release 50	Volume Recovered 45
Source of Release 4" Check Valve froze and broke during the thaw out process.	Date and Hour of Occurrence 2/07/2011	Date and Hour of Discovery 2/07/2011 - AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD/Artesia	
By Whom? Amanda Trujillo - Yates Petroleum Corporation	Date and Hour 02/09/2011 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*

4" Check Valve froze and broke during the thaw out process. Release was held inside lined berm. Vacuum truck was dispatched to pick up standing fluids.

Describe Area Affected and Cleanup Action Taken.*

An approximate size of 20' x 20' was impacted. Release was held inside lined berm. Vacuum truck was dispatched to pick up standing fluids. **Depth to Ground Water: >50' (approx. 65', per New Mexico State Engineers office); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 10. Based on site ground water quality and enclosed analytical results.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By: <i>Mike Bratcher</i>	
Title: Environmental Scientist	Approved by District Supervisor:	
E-mail Address: atrujillo@yatespetroleum.com	Approval Date: MAR 26 2012	Expiration Date: <i>N/A</i>
Date: Wednesday, March 16, 2011 Phone: 575-748-4310	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-734