District 1 1625 N. French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 R10 Brazos Road, Aztec, NM 87410 District IV 1220 S. St Francis Dr , Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

REC	Eľ	V	E	D
MAR	- 8	21	012	

Form C-141 evised October 10, 2003

NMOGD ABDTESHAmmate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action												
NMLB1208055446					<b>OPERA</b>	FOR		🔀 Initial Report 🗌 Final Re			eport	
Name of Company: Linn Operating 269324					Contact: Joe							
Address: 2130 W. Bender Hobbs, NM 88240						No.: 575-738-17		<del></del>				
Facility Name: West B #4 Battery / West B #38H			Facility Typ	e: Tank Battery	/ Inject	lon			]			
Surface Owner: Federal Mineral Owner: Fe				Federal         API No.: 3001526001								
				LOCA		N OF RE						
Unit Letter F	Section 10	Township 17S	Range 31E	Feet from the 2085	North	n/South Line North	Feet from the 1980		/est Line /est	-		
Latitude: 32.850600037686 Longitude: -103.859729591584												
				NAT	URE	OF REL						
Type of Release: Oil / Produced Water Source of Release: Circulating Line						ume of Release: 165 / 25Volume Recovered: 160 / 22e and Hour of Occurrence:Date and Hour of Discovery:						
Source of Re	lease: Circu	lating Line				03/07/2012	-	e:		2 8:00am	covery:	
Was Immediate Notice Given?					If YES, To		L					
By Whom <sup>9</sup> I	Dennis Potte	r				Date and I	lour 03/07/2012		-			
Was a Watercourse Reached?				If YES, Vo	olume Impacting t	he Wate	rcourse.					
If a Waterra		Dacted, Descri										
Describe Cat	use of Proble	em and Remed	dial Action	n Taken.*: 2" line	at head	der was corroc	led, and busted.					
Describe Area Affected and Cleanup Action Taken.* : Oil picked up from inside containment. Further remedial action pending.												
regulations a public health should their or the enviro	Il operators or the envir operations h nment. In a	are required to onment. The ave failed to a	o report ar acceptanc dequately CD accep	nd/or file certain r ce of a C-141 report investigate and r	elease i ort by tl emedia	notifications a ne NMOCD m te contaminat	knowledge and u nd perform correc arked as "Final R- on that pose a three the operator of the	tive acti eport" d eat to gr responsi	ons for rel oes not rel ound wate bility for c	eases which ieve the ope r, surface was compliance w	may endanger rator of liability ater, human health vith any other	h
Signature:	e: Joe Herna	<u>ndez</u>	Ž.			Approved by	OIL CONS Signed By District Supervise		A.1	DIVISIO		
Title: Produc						Approval Da	1AR 2 0 20	12	Expiration	Date:		
E-mail Addr Date: 03/08/ * Attach Add	2012		hone: 575	-942-9492	<b>C</b>	Conditions o Remediati delines. SU		IATIO	N –	Attached	)- 106 o	)
						·						

## Bratcher, Mike, EMNRD

From:	Theresa McCracken [TMcCracken@linnenergy.com]
Sent:	Thursday, March 08, 2012 9:55 AM
To:	Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc:	Daniel Frick; Ron Ragland
Subject:	Linn- West B #4 Battery/West B #38 Inj Initial C-141
Attachments:	West B #4 Battery - West B #38 Inj. Initial C-141.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,

*Theresa McCracken* LINN Operating 2130 W. Bender Blvd Hobbs, NM 88240 (575)738-1739 tmccracken@linnenergy.com

·