District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenus, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

nMLB1208651788				OPERATOR				\boxtimes	Initial	l Report	\boxtimes	Final Report
Name of Company				OGRID Nun	iber	Contact						
Yates Petroleum Corporation				25575		Robert Asher						
Address						Telephone No.						
104 S. 4 TH Street						575-748-1471						
Facility Name API Number						Facility Typ	e					•
Glow Worm ALX Federal Battery 30-015-35313						Battery		····				
Surface Ox	mer			Mineral C)wner			Ť	Lease N	Ĭo.		
					Federal			- 1	VM-81			
-				LOCA	TTO	N OF RE	LEASE					
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/West	t Line	County		
В	4	238	31E							Eddy		
	<u></u>	<u> </u>	<u> </u>					<u> </u>				
Latitude 32.04040 Longitude 103.20855												
NATURE OF RELEASE												
Type of Rele	ase					Volume of Release			Volume Recovered			
Produced Water									500 B/PW			
Source of Release										d Hour of Discovery		
Fiberglass Ta						3/8/2012; AM 3/8/201				2; AM		
Was Immedi	ate Notice (If YES, To Whom?						
			Yes <u>L</u>	No Not Re	equired	ed Mike Bratcher/NMOCD II						
By Whom?						Date and Hour						
		oleum Corpor	ation			3/8/2012; AM (Voicemail & e-mail)				RE		MED
Was a Water	course Rea		1 1/- A	7 Nr.		1	olume Impacting	the Watered	ourse.	to Afficiants A	THE PROPERTY OF	. W drawn than
If a Watergo	vene xxxxx I		Yes 🔯			N/A				MAR 16 2012		
If a Watercourse was Impacted, Describe Fully.* N/A												
Describe Cause of Problem and Remedial Action Taken.*											DA	RTESIA
Water pump failed to start, causing tank to run over. Vacuum trucks called to the location. Isolated tank, pump started.												
		and Cleanup										
				eased water contai								
				r the NMOSE/IS								
Corporation			etea smo	unts of produced	water	, reiease with	in Dermed/lined	containme	nt area	, Yates Pet	roleum	1
			ven abov	e is true and comp	lete to t	the best of my	knowledge and r	understand t	hat pur	suant to NN	40CD :	miles and
				nd/or file certain r								
public health	or the envi	ronment. The	acceptan	ce of a C-141 repo	ort by th	ie NMOCD m	arked as "Final R	Report" does	not rel	ieve the ope	erator o	of liability
should their	operations h	nave failed to	adequately	investigate and r	emedia	te contaminat	ion that pose a thi	reat to groun	nd wate	r, surface w	ater, h	uman health
or the enviro	nment. In a	addition, NMC	OCD accep	otance of a C-141	report o	loes not reliev	e the operator of	responsibíli	ity for c	ompliance	with an	ly other
federal, state	, or local la	ws and/or regi	ilations.									
		\sim	\sim		ĺ		OIL CON	SERVA	<u>TION</u>	DIVISI	<u> NC</u>	
Signature:		$C \supset_{AA}$	() .	0								
Orginatus. C.		مري	\\\	^-		A J b.	Signed By District Supervis	11/4	R) KM	WHLER_	_	
Printed Nam	e: Robert A	sher				Approved by	District Supervis	SOT:				
Title: Enviro	nmental Re	gulatory Ager	ıt			Approval Date: Approv						
~~							4	1.4				
E-mail Addr	ess: boba@	yatespetroleur	n.com		\dashv	Conditions of Approval: NIA Attached						
Date: Friday				75-748-4217		2RP- /06	<u> </u>	Vinay				
		ets If Necess	агу							10	1	1010
		•								de	13 -/	1068

Bratcher, Mike, EMNRD

From:

Bob Asher [BobA@yatespetroleum.com] Thursday, March 08, 2012 8:12 AM

Sent:

To:

Bratcher, Mike, EMNRD; Dade, Randy, EMNRD; 'BLM (Jim Amos)'

Cc:

Amanda Trujillo; Amber Cannon; Jeremy Haass; Jerry Fanning; Lisa Norton

Release: Glow Worm ALX Federal Battery Subject:

Yates Petroleum Corporation is reporting a release at the following location.

Glow Worm ALX Federal Battery 30-015-35313 Section 4, T23S-R31E Eddy County, New Mexico

Released: 500 B/PW; Recovered: In Progress; Vacuum Trucks picking up released water, battery is bermed and lined (all produced water contained inside battery).

Cause of release not known at this time.

A Form C-141 Initial/Final Report will be submitted with complete information.

Thank you.

Robert Asher

Environmental Regulatory Division Yates Petroleum Corporation 105 South Fourth Street Artesia, NM 88210 575-748-4217 (Direct) 575-365-4021