

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD

MAY 29 2012

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa	
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126	
Facility Name SEMU Permian Skaggs Pool Water Line	Facility Type Produced water transfer line	
Surface Owner New Mexico	Mineral Owner BLM	API No. 30-025-06248

LOCATION OF RELEASE

Unit Letter K	Section 24	Township 20S	Range 37E	Feet from the 1980	North/South Line South	Feet from the 1980	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude N 32 33.4038 Longitude W 103 12.4260

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 370	Volume Recovered 340
Source of Release PW transfer line	Date and Hour of Occurrence 5/27/12 8:30 am	Hour of Discovery 5/27 9 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? E. L. Gonzales	
By Whom? Jesus A Sosa	Date and Hour May 28, 2012 8:35 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Leak on a 4" fiberglass line (30+ years) that had a Victaulic clamp bolt corroded and broken causing produced water to be released. MSO notified immediate supervisor and called for a vacuum truck. Total recovered fluid was 340 BPW

Describe Area Affected and Cleanup Action Taken.*

Area of release is approximately 30 feet X 90 feet all on pasture. Are will be delineated and a work plan submitted to NMOCD for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa		Approved by Environmental Specialist: 	
Title: HSER Lead	Approval Date: 5/30/12	Expiration Date: 7/30/12	
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval: SUBMIT FINAL C-141 BY 7/30/12		Attached <input type="checkbox"/>
Date: 5/29/2012	Phone: (505)391-3126	IRP-5-12-2817	

* Attach Additional Sheets If Necessary

MAY 30 2012