District I
1625 N French Dr , Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised August 8, 2011
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Release Notification and Corrective Action

NMLB 12150 50616						OPERATOR Initial Report Final R						Final Repor	
Name of Company Apache Corporation 873						Contact Natalie Gladden							
						Telephone No. 575-390-4186							
Facility Name NB Tween #16						Facility Type Production well							
Surface Owner Concho Resources Mineral Owner S						State API No. 30-015-38406							
				LOCA	TIO	N OF REI	FASE				_		
							South Line Feet from the East/West Line County						
		_				20000							
H 25 178 28E 1650' FNL					990'	FEL	. Eddy						
LatitudeLongitude													
	NATURE OF RELEASE												
Type of Release Oil							Volume of Release 10 Volume Recovered 0						
Source of Release BOP Failure							Date and Hour of Occurrence Date and Hour of Discovery 03/12/12						
Was Immediate Notice Given?							If YES, To Whom?						
☐ Yes ☐ No ☐ Not Required							Bratcher						
By Whom? Natalie						Date and Hour 3/21/02 824am							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If - Waterson	moo uyoo laa						FRE		EIVE	1			
If a Watercourse was Impacted, Describe Fully.*													
APR 3 0 2012													
										40TE0	1.0		
Describe Cause of Problem and Remedial Action Taken.*													
Workover rig on well shut in BOP Valves the evening before but it did not seal correctly. Seals were replaced and fluid was recovered.													
Describe Area Affected and Cleanup Action Taken.* Site will be remediated and the NMOCD Guidelines will be followed to closure of this release.													
Site will be remediated and the 1910-of Outdenines will be followed to closure of this release.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations al	l operators	are required to	report an	d/or file certain re	elease no	otifications ar	nd perform correct	tive actions	for rele	eases which	may en	danger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
federal, state,	or local lay	vs and/or regu	lations.				OII COM	CEDVAT	IONI	DIVICIO	NT.		
/ hatail lands. I						OIL CONSERVATION DIVISION							
Signature:	$-\omega$	ullu	Approved by Environmental Specialist:										
Printed Name: Natalie Gladden							Approved by Environmental Specialist:						
							Approval DMAY 2 9 2012 Expiration Date:						
E-mail Address: natalie.gladden@apachecorp.com						Conditions of Approval: Attached							
Date: 3/26/12 Phone:575-390-4186							- diation per OCD Rules &						
Date: 3/26/12 Phone:575-390-4186 Attach Additional Sheets If Necessary Attach Additional Sheets If Necessary PROPOSAL NOT LATER THAN: PROPOSAL NOT LATER THAN: PROPOSAL NOT LATER THAN:											1211		
					PR	OPOSAL NO	9/2012	<u> </u>	C	メベト	-//	34	
						6/2	110			•		ſ	

Bratcher, Mike, EMNRD

From:

Gladden, Natalie [Natalie.Gladden@apachecorp.com]

Sent:

Wednesday, March 21, 2012 7:24 AM

To:

Bratcher, Mike, EMNRD

Cc:

Stockton, Billy

Subject:

NB Tween #16

Importance:

High

This morning the leak was found. We are doing a maintenance workover to try to clean up some scale build-up. The BOP valves were shut last night, but obviously did not seal correctly. 10bbls of oil was released with no recovery.

NB Tween #16 H-25-17S-28E 1650' FNL and 990' FEL 30-015-38406

C141 to follow.

Natalie Gladden

Apache Corporation EHS Environmental Tech New Mexico District

Cell: 575-390-4186

Office: 575-394-1503 x 1258

Fax: 575-394-2425

Email: natalie.gladden@apachecorp.com