District I 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

JUN 04 2012

RECEIVED

Form C-141 evised October 10, 2003

NMOCD ARTEGINA Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

1220 South St. Francis Dr. Santa Fe, NM 87505 Release Notification and Corrective Action

nMLB 12164499		OPERATOR					al Report	\boxtimes	Final Repor			
Name of Company	137	Contact Pat Ellis										
Address 550 W)1	Telephone l	No. 432-	230-00	7 7							
Facility Name .		Facility Typ	e Tani	k Batter	гу							
Surface Owner Federal Mineral Owner					Lease No. (API)# 30-015-35816 Closest Well							
			LOC	ATIO	OF RE	LEASE	•	<u> </u>	······································			
Unit Letter Section F 15	nit Letter Section Township Range Feet from the No								East/West Line County Eddy			
			Latitude 32	2 49.25	Longit	ude 103 48.20						
			NAT	TURE	OF REL							
Type of Release Oil						Volume of Release 10bbls Volume Recovered						
Source of Release Oil tank						Hour of Occurrenc	e		Hour of Di 2 8:00 a.r		<i>r</i>	
Was Immediate Notice Given?						Whom?		03:10:401	1.6 UU.0 a.1	1,		
		Yes 🗵	No 🛛 Not R	equired								
By Whom?						Date and Hour						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes ⊠ No									*			
If a Watercourse was In	pacted, Descr	ibe Fully.*	k		1			***************************************	×			
Describe Cause of Prob	lem and Reme	dial Action	1 Taken *									
Equalizer valve was clo	sed causing the	e oil tank t	o fill and overflo	w. The	equalizers ha	ve been opened.						
Describe Area Affected	and Cleanup /	Action Tak	cen.*									
Initially 10bbls of oil w contaminated gravel has	been removed	d as necess	sary. We have a	lded fres	h gravel to th	e facility. This ta	nk batte	ry has been	returned t	o its pri	or condition.	
I hereby certify that the regulations all operators public health or the env should their operations or the environment. In federal, state, or local la	are required to a representation are failed to a reddition, NMC	o report ar acceptance adequately OCD accep	nd/or file certain te of a C-141 rep investigate and	release n ort by th remediat	otifications a e NMOCD m e contaminat	nd perform correct tarked as "Final Rition that pose a thr	ctive acti eport" d eat to gr	ions for rel loes not rel round wate	eases whic ieve the op r, surface v	h may e erator o vater, hu	endanger of liability uman health	
		OIL CONSERVATION DIVISION Signed By Wile Branch										
Signature: Printed Name: Josh Russo					Approved by District Supervisor:							
Title:		oordinator			Approval Da	ĮŲN 12 20	12 1	Expiration	Date: N	4		
· ·						Conditions of Approval: NA Attached						
Date: 06/01/2012	Phone			1			711	ルレン	1			
Date. 00/01/2012	ruone	432-	212-2399	- 1			1 10	LP .	I			

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Friday, June 01, 2012 3:02 PM

To: Bratcher, Mike, EMNRD; Jim Amos office (jamos@blm.gov); Terry Gregston

(tgregsto@blm.gov)

Subject: C-141 Initial/Final Report - Skelly 968 TB

Attachments: SKELLY 968 TANK BATTERY -- DATE OF RELEASE -- 05-18-2012.pdf

Please see attached the C-141 Initial/Final Report for a release that we had inside a lined facility.

Thank you,

Joshua Russo

HSE Coordinator 550 W. Texas Ave, Suite 100 Midland, Texas 79701 Phone: (432) 683-7443

Cell: (432) 212-2399

jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.