

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nJMW 1218053031 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: <b>Apollo Energy, LP</b> <u>248192</u>	Contact: <b>Tommy Wright</b>
Address: <b>4823 Ihles Road, Lake Charles, LA 70605</b>	Telephone No.: <b>337-502-5227</b>
Facility Name: <b>Russell USA #20</b>	Facility Type

Surface Owner: <b>BLM</b>	Mineral Owner: <b>BLM</b>	API No. <b>3001502369</b>
---------------------------	---------------------------	---------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>M</b>	<b>13</b>	<b>20S</b>	<b>28E</b>	<b>330</b>	<b>South</b>	<b>1,005</b>	<b>West</b>	<b>Eddy</b>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release: <b>Water &amp; Oil</b>	Volume of Release: <b>20 bbls</b>	Volume Recovered: <b>Initial Report</b>
Source of Release: <b>Flow lined</b>	Date and Hour of Occurrence: <b>unknown</b>	Date and Hour of Discovery: <b>6/18/12</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Jennifer Van Curen -BLM</b>	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	


If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

**Rupture in flowline**

Describe Area Affected and Cleanup Action Taken.\*

**Immediate Area of ruptured flowline. Will remove any liquid and soil as necessary.**



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Thomas Wright</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Thomas Wright</b>	Signed By: <u>Mike Brannon</u>	
Title: <b>Executive Vice President</b>	Approved by Environmental Specialist:	
E-mail Address: <b>tommyw@doreenergy.com</b>	Approval Date: <b>JUN 28 2012</b> Expiration Date:	
Date: <b>6/19/12</b> Phone: <b>337-502-5227</b>	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

7/28/12

2RP-1199