

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company COG Operating LLC		Contact Pat Ellis
Address 550 W. Texas, Suite 1300 Midland, Texas 79701		Telephone No. (432) 230-0077
Facility Name Harper State Tank Battery		Facility Type Tank Battery
Surface Owner State	Mineral Owner	Lease No. API# 30-015-30831

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	16	17-S	30-E					Eddy

Latitude N 32 49.728° Longitude W 103 58.150°

NATURE OF RELEASE

Type of Release: Produced Fluid	Volume of Release 2 bbls oil 8 bbls produced water	Volume Recovered 1 bbls oil 6 bbls produced water
Source of Release Water transfer line	Date and Hour of Occurrence 11/21/2011	Date and Hour of Discovery 11/21/2011 4:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Josh Russo	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A




Describe Cause of Problem and Remedial Action Taken.*

The water transfer line leaked inside the facility. The line has been repaired and returned to service.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech inspected site and collected samples to define spills extent. Soil with TPH concentrations above the RRAL and/or elevated chloride concentrations was removed and hauled away to Controlled Recovery, Inc., Hobbs, NM. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Signed By:  Approved by District Supervisor:	
Title: Project Manager	Approval Date: AUG 10 2012	Expiration Date: N/A
E-mail Address: ike.tavarez@tetrattech.com	Conditions of Approval: 	Attached <input type="checkbox"/>
Date: 3-1-12	Phone: (432) 682-4559	

Attach Additional Sheets If Necessary

2RP-968