

District I
1625 N French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

AUG 31 2012

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
NMOCD ARTESIA

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMK 1225651459

277558 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Lime Rock Resources II-A, L.P.	Contact	Michael Barrett
Address	1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No.	575-623-8424
Facility Name	Atoka San Andres Unit #100	Facility Type	Injection Line
Surface Owner	Fanning Farms	Mineral Owner	Unknown
		API No.	30-015-00298

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	12	18S	26E	990'	FNL	330'	FWL	Eddy

Latitude 32.767048 Longitude 104.342689

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	95 bbls	Volume Recovered	0 bbls
Source of Release	Injection Line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	8/20/2012 @ 3:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD		
By Whom?	Michael Barrett	Date and Hour	8/21/2012 @ 11:30 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Injection line leak. Line has been isolated and taken out of service.
Waiting on agreed work plan before any remediation begins.

Describe Area Affected and Cleanup Action Taken.*

Alfalfa field.
No standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Michael Barrett	Approved by Environmental Specialist	Signed By 
Title:	Production Supervisor	Approval Date:	SEP 12 2012
E-mail Address:	mbarrett@limerockresources.com	Expiration Date:	
Date:	08/21/2012	Phone:	575-623-8424
		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

October 12th 2012

2RP-1289