

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 27 2012

Form C-141
Revised October 10, 2003

NMOCD ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action



nJWW 1228952965		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company		COG OPERATING LLC 229137	Contact	Pat Ellis	
Address		550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077	
Facility Name		GJ West Coop Trunkline	Facility Type	Trunkline	
Surface Owner State		Mineral Owner		Lease No. (API#) 30-015-25492 Wells tied into trunkline 30-015-03163	

LOCATION OF RELEASE

Unit Letter B	Section 28	Township 17S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 48.512 Longitude 104 04.600

NATURE OF RELEASE

Type of Release Produced water w/ skim oil	Volume of Release 8bbls	Volume Recovered 5bbls
Source of Release Trunkline	Date and Hour of Occurrence 09/20/2012	Date and Hour of Discovery 09/20/2012 11.00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken *		
Corrosion caused a hole to develop in our GJ West Coop Unit #74 and 125 trunkline. A temporary clamp has been added to this trunkline until we are able to replace it.		
Describe Area Affected and Cleanup Action Taken.*		
Initially 8bbls were released from the corroded trunkline and we were able to recover 5bbls with a vacuum truck. A temporary clamp has been added to this trunkline until we are able to replace it. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Approved by District Supervisor:	Signed By: 
Title: HSE Coordinator	Approval Date: OCT 15 2012	Expiration Date:
E-mail Address: jrusso@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/27/2012 Phone: 432-212-2399		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
Nov. 15, 2012

2RP-1322

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Thursday, September 27, 2012 1:25 PM
To: Bratcher, Mike, EMNRD
Cc: Ike Tavaréz (ike.tavaréz@tetrattech.com); Robert Grubbs (Robert.Grubbs@tetrattech.com); Tom Franklin (tom.k.franklin@tetrattech.com)
Subject: C-141 Initial Report- GJ West Coop Unit Trunkline
Attachments: GJ WEST COOP UNIT TRUNKLINE (#74 - #125 WELLS) -- DATE OF RELEASE -- 09-20-2012.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at our GJ West Coop Unit Trunkline. We plan to sample the spill area as soon as we can.

Thank you,

Joshua Russo

HSE Coordinator
432.683.7443 (main)
432.685.4381 (direct)
432.212.2399 (cell)
jrusso@concho.com

Mailing Address:

One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.