

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised October 10, 2003

NOV 06 2012

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Citation X Federal Com #1H	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-025-39960

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	8	19S	32E					Eddy, LEA

Latitude 32 40.240 Longitude 103 47.158

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	80bbls	Volume Recovered	75bbls
Source of Release	Filter pot	Date and Hour of Occurrence	10/26/2012	Date and Hour of Discovery	10/26/2012 12:30 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Josh Russo	Date and Hour	10/29/2012 12:40 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The 1 inch drain line threads on the filter pot valve failed causing the release of fluid into the facility. The valve and pipe have been replaced.

Describe Area Affected and Cleanup Action Taken.\*

Initially 80bbls were released into the lined facility at the Citation X Federal Com #1H Tank Battery. We were able to recover 75bbls with a vacuum truck. All free fluid has been recovered from the release. All free fluid remained inside the lined facility. We have removed the contaminated gravel, steam cleaned the liner, and replaced fresh gravel throughout the facility as necessary. The facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Josh Russo	Approved by District Supervisor	Jeffrey Sekins
Title:	Senior Environmental Coordinator	Approval Date:	11/7/12
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	11/05/2012	Conditions of Approval:	-
Phone:	432-212-2399	Attached:	<input type="checkbox"/>
		RP-11-12-2863	

\* Attach Additional Sheets If Necessary

NOV 07 2012