


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

Operator ☒ Initial Report ☐ Final Report

Name of Company COG OPERATING LLC **229137** **Contact** Pat Ellis
Address 600 West Illinois Avenue, Midland, TX 79701 **Telephone No.** 432-230-0077
Facility Name Brigham H 3 **Facility Type** Flowline

Surface Owner Federal **Mineral Owner** **Lease No. (API#)** 30-015-30677

LOCATION OF RELEASE

Unit Letter 11	Section 21	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.81998 **Longitude** 103.98310

NATURE OF RELEASE

Type of Release Produced water w/ skim oil	Volume of Release 13bbls	Volume Recovered 12bbls
Source of Release Flowline	Date and Hour of Occurrence 11/02/2012	Date and Hour of Discovery 11/02/2012 3:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A steel line corroded and released fluid into the adjacent pasture area. We have added a temporary clamp to the line and will replace the joint with a new section.		
Describe Area Affected and Cleanup Action Taken.* Initially 13bbls of fluid were released from the steel line and we were able to recover 12bbls with a vacuum truck. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Approved by District Supervisor:	Signed By:
Title: Senior Environmental Coordinator	Approval Date: NOV 14 2012	Expiration Date:
E-mail Address: jrusso@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/13/2012 Phone: 432-212-2399		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
Dec. 14, 2012

2RP-1399

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Tuesday, November 13, 2012 3:46 PM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov); Jim Amos office (jamos@blm.gov)
Cc: Ike Tavarez (ike.tavarez@tetrattech.com); Robert Grubbs (Robert.Grubbs@tetrattech.com); Tom Franklin (tom.k.franklin@tetrattech.com)
Subject: C-141 Initial Report - Brigham H 3 Flowline
Attachments: BRIGHAM H 3 FLOWLINE -- DATE OF RELEASE -- 11-02-2012.pdf

Please see attached the C-141 Initial Report for a release that occurred on 11/02/2012. We plan to assess the spill area timely.

Thank you,

Joshua Russo

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

jrusso@concho.com

Mailing Address:

One Concho Center

600 W. Illinios Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.