


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JMW 1234250637 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Firecracker State #2 Tank Battery	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-37506

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	14	17S	28E					Eddy

Latitude 32.83085 Longitude 104.1438

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbbls	Volume Recovered	19bbbls
Source of Release	Swedge on water pump	Date and Hour of Occurrence	11/17/2012	Date and Hour of Discovery	11/17/2012 7:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Due to vibration, the 4" to 1" swedge broke on the top of the water pump inside the facility. The broken swedge has been replaced with a new swedge.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbbls of produced water were released from the broken swedge on top of the water pump inside the facility. We were able to recover 19bbbls with a vacuum truck. The entire release was completely contained inside the lined facility walls of the tank battery. All free fluid has been recovered and any contaminated gravel has been removed. Fresh gravel has been added to the facility as necessary. This facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Approved by District Supervisor:		Signed By:	
Title: Senior Environmental Coordinator		Approval Date: DEC 07 2012		Expiration Date:	
E-mail Address: jrusso@concho.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 11/28/2012 Phone: 432-212-2399					

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
Jan. 7th 2013

2RP-1436

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Wednesday, November 28, 2012 2:44 PM
To: Bratcher, Mike, EMNRD
Subject: C-141 Initial / Final Report - Firecracker State Tank Battery
Attachments: FIRECRACKER STATE TANK BATTERY -- DATE OF RELEASE -- 11-17-2012.pdf

Mr. Bratcher,

Please see attached the C-141 Initial / Final Report for a release that occurred on 11/17/2012. This release occurred inside a lined facility.

Thank you,

Joshua Russo

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

jrusso@concho.com

Mailing Address:

One Concho Center

600 W. Illinios Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.