District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action OPERATOR 133 33029 ☐ Initial Report Final Report 16696 Contact Leslie V. Moreno Name of Company OXY USA Inc. Address 1017 W. Stanolind Rd. Telephone No. (575) 397-8247 Facility Name Goodnight 27 #1 Facility Type Production Battery Mineral Owner Lease No. API 30-015-22157 Surface Owner LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County 238 29E 660 198 W Eddy Longitude Latitude NATURE OF RELEASE Type of Release Temp. Flare Volume of Release 200 MCF Volume Recovered 0 Source of Release Flare Date and Hour of Occurrence Date and Hour of Discovery 12/2411 @ 12/24/11 @ 0600 hrs to 12/24/11 0600 hrs @ 2200 hrs Was Immediate Notice Given? If YES, To Whom? Elidio Gonzales By Whom? Leslie V. Moreno, HES Administrative Assistant Date and Hour 12/30/11 @ 9:48 am Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. N/A Yes No If a Watercourse was Impacted, Describe Fully.* N/A RECEIVED JAN **09** 2012 Describe Cause of Problem and Remedial Action Taken.* Oxy began flaring due to DCP emergency shut down. NMOCD ARTESIA Describe Area Affected and Cleanup Action Taken.* N/A I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Accepted for record Signature: **NMOCD** Approved by District Supervisor: Printed Name: Leslie V. Moreno Title: HES Administrative Assistant Approval Date: Expiration Date: E-mail Address: Leslie_Moreno@oxy.com Conditions of Approval: Attached

Phone: (575) 397-8247

Moreno, Leslie V (Preferred Personnel)

From:

Moreno, Leslie V (Preferred Personnel)

Sent: To: Friday, December 30, 2011 9:48 AM

Subject:

'ElidioL.Gonzales@state.nm.us'

flaring

Hello,



I hope you had a great Christmas break © Since I was out, there were flares:

CE Lamunyon #1 Battery (750 MCF) and Elson Battery (43 MCF) starting 12/22/11 due to Southern Union Gas shutting down for line repairs.

Cypress 34 & Goodnight 21 Batteries (MCF's unknown) due to DCP emergency shut down on 12/24/11.

As soon as I get all the proper information for the C-129's I will send them to you. I'm sorry for the delay.

Thank you!

Leslie V. Moreno HES Administrative Assistant OXY Permian 1017 W. Stanolind Rd. Office: (575) 397-8247

Cell: (575) 605-5100 Fax: (575) 397-8234