


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*njm* 1301853525

**OPERATOR**

☒ Initial Report

☐ Final Report

Name of Company : Chevron USA <i>241333</i>	Contact: Amy Barnhill
Address: 2401 Avenue O Eunice, NM 88231	Telephone No.: 432-940-8524
Facility Name: Catclaw Draw Unit #18	Facility Type: Tank Battery

Surface Owner: State of NM	Mineral Owner: State of NM	API No. <i>30-015-33320</i>
----------------------------	----------------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	23	21-S	25-E		1310		1310	Eddy

Latitude: 32.46832 Longitude: -104.36972

**NATURE OF RELEASE**

Type of Release: Oil and Water  
Source of Release: Tank Valve

Volume of Release: 951

Volume Recovered: 5bbls

Date and Hour of Occurrence:  
12-2-2012

Date and Hour of Discovery:  
12-2-2012 @ 11:48am

Was Immediate Notice Given?

☒ Yes ☐ No ☐ Not Required

If YES, To Whom?

Called 575-393-6161 E.L. Gonzales

By Whom? Amy Barnhill

Date and Hour: 12-3-2012 @ 2:45 pm

Was a Watercourse Reached?

☐ Yes ☒ No

If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A ball valve in the back of the tank has a hole in it. F.S. found the leak at 11:48 am. He immediately plugged the valve and called a vacuum truck

Describe Area Affected and Cleanup Action Taken.\*

A vacuum truck picked up a total of 5 bbls fluid and 2.951 bbls soaked into the gravel. Further remediation will be performed in accordance with a NMOCD approved remediation plan.

Total spill volume was 7.951 Bbls, 4.77 water and 3.18 oil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:

Printed Name: Amy Barnhill

Approved by Environmental Specialist:

Signed By *Mike Beaman*

Title: HE Specialist

Approval Date: **JAN 18 2013**

Expiration Date:

E-mail Address: ABarnhill@chevron.com

Conditions of Approval:

Attached ☐

Date: 12-3-2012

Phone: 432-940-8524

Remediation per OCD Rule &  
Guidelines. **SUBMIT REMEDIATION**

**PROPOSAL NO LATER THAN:**  
**February 18, 2013**

*2RP-1507*

\* Attach Additional Sheets If Necessary

**Bratcher, Mike, EMNRD**

---

**From:** Barnhill, Amy D. <ABarnhill@chevron.com>  
**Sent:** Thursday, January 10, 2013 10:18 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** FW: Lentini 1 Fed Batt and Catclaw Draw Unit #18 C-141s  
**Attachments:** C-141 Form 12-1-12.doc; C-141 Form 12-2-2012.doc

*Please see attached forms that I sent to the wrong department. Please forgive my ignorance, I am new. Thank you for your patience as I learn.*

*Thank you,*  
**Amy Barnhill, CBES**  
Health and Environment Specialist  
MCBU Permian South Area  
Eunice, Ft. Stockton, McElroy  
Office: 432-558-1937 Cell: 432-940-8524  
E-Mail: [ABarnhill@chevron.com](mailto:ABarnhill@chevron.com)

---

**From:** Leking, Geoffrey R, EMNRD [<mailto:GeoffreyR.Leking@state.nm.us>]  
**Sent:** Monday, December 31, 2012 12:06 PM  
**To:** Barnhill, Amy D.  
**Cc:** Bratcher, Mike, EMNRD  
**Subject:** Lentini 1 Fed Batt and Catclaw Draw Unit #18 C-141s

Amy

The above referenced C-141s were received in District 1 on December 20, 2012. The spills were discovered on December 1 and 2, so the C-141s should have been submitted by the 16<sup>th</sup> and 17<sup>th</sup> respectively. However, and more importantly, both of the above referenced sites are in District 2. Please resend the C-141s to Mike Bratcher, Environmental Specialist, NMOCD-District 2. Thank you .

Geoffrey Leking  
Environmental Specialist  
NMOCD-Hobbs  
1625 N. French Drive  
Hobbs, NM 88240  
Office: (575) 393-6161 Ext. 113  
Cell: (575) 399-2990  
email: [geoffreyr.leking@state.nm.us](mailto:geoffreyr.leking@state.nm.us)