


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

JMW1302240439 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ West Coop #210	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-36703

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	16	17S	29E					Eddy

Latitude 32 50.334 Longitude 104 04.994

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	4bbls Oil 6bbls Produced water	Volume Recovered	3bbls Oil 5bbls Produced water
Source of Release	Fire tube gasket	Date and Hour of Occurrence	01/03/2013	Date and Hour of Discovery	01/03/2013 9:30 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

There was a fire tube gasket failure on the heater treater inside the facility. The heater treater has been drained and the fire tube has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of produced fluids were released and we were able to recover 8bbls with a vacuum truck. The release was completely contained inside the lined facility. All free fluid has been recovered and contaminated gravel has been removed. Fresh gravel has been added to the facility as needed. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By:
Title:	Senior Environmental Coordinator	Approval Date: JAN 22 2013	Expiration Date:
E-mail Address:	jrusso@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	01/15/2013	Phone:	432-212-2399

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

February 22, 2013

2RP-1512

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Tuesday, January 15, 2013 2:30 PM
To: Bratcher, Mike, EMNRD
Subject: C-141 Initial/Final Report - GJ West Coop Unit #210 Tank Battery
Attachments: GJ WEST COOP #210 TANK BATTERY -- DATE OF RELEASE -- 01-03-2013.pdf

Mr. Bratcher,

Please see attached a C-141 Initial/Final Report for a release that occurred at our GJ West Coop Unit #210 Tank Battery on 01/03/2013. This release occurred inside a lined facility.

Thank you,

Joshua Russo

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

jrusso@concho.com

Mailing Address:

One Concho Center

600 W. Illinios Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.