

# RECEIVED

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

JAN 15 2013  
State of New Mexico  
Energy Minerals and Natural Resources  
NMOCD ARTESIA  
Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

nJMW 130 2332891 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Range operating 227588	Contact	Rod Garcia
Address		Telephone No.	575-706-9132
Facility Name	South Culbraz Bluff 2-B Lease	Facility Type	Flowline
Surface Owner	Mineral Owner	API No.	

## LOCATION OF RELEASE \*30-015-22591

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
8	14	23S	28E	N/A	N/A	N/A	N/A	Cddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release	Produced water / BS	Volume of Release	20-30 BBL	Volume Recovered	0
Source of Release	Flowline in pasture	Date and Hour of Occurrence	12.29	Date and Hour of Discovery	12.29 3:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Tasha Melancon	Date and Hour	1.3.2013	2:30 p.m.	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Flowline in pasture began to leak causing 20-30 BBL of produced water and B.S. to flow onto ground. No fluid was standing in pasture, backhoe began cleaning up pasture area by scraping and stock piling.

Describe Area Affected and Cleanup Action Taken.\*

Pasture area Northeast of Reid Wells #1, took equipment to location dug out and hauled visible contamination to disposal

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: Rod Garcia  
Printed Name: Rod Garcia  
Title: Production Supervisor I  
E-mail Address: rgarcia@range-resources.com  
Date: 12-31-2012 Phone: 575-706-9132

Approved by Environmental Specialist: Mike Brennan  
Signed By  
Approval Date: JAN 23 2013 Expiration Date:  
Conditions of Approval: Attached ☐

Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

Feb. 23, 2013

2RP-1517

\* Attach Additional Sheets If Necessary