
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505



Release Notification and Corrective Action														
MM	1302	23488	552				OPERA	OR	\boxtimes	Initia	al Report	Fina	l Report	
Name of Co		Oxy Permia		1924	63			hristopher Jone						
		Commerce Dr				Telephone No. (575) 628-4121								
Facility Nar		Ranch Knoll	8 Federa			Facility Typ	e !							
Surface Ow	ner BLM	1		Min	eral O	wner	Lease No. API#30-015-32295							
				L	OCA	TION	OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from	the	North/S	South Line	Feet from the	East/West	Line	County			
G	8	22S	24E	2120) {	ì	North	1600	East		Eddy Cour	nty, NM		
				Latitude]	N 32 4	0723°	Longitu	ide W 104.5170	00					
				1	1		_		<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>					
Type of Relea	ase Produ	uced water			NAI	URE	Volume of Release 100 bbls Volume Recovered 70 bbls							
Source of Rel		steel water line	charge side	of 3 p	hase	Date and Hour of Occurrence Date and Hour of Discovery								
separator	· \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	7' 0				1/15/13								
Was Immedia	ite Notice C	лven?	Whom? her- OCD, James	Amos-BL	М.									
	·		No 🗆			Terry Gregston-BLM								
By Whom? Was a Watero	Christoph				-	Date and Hour 1/16/13 @ 7:20 am If YES, Volume Impacting the Watercourse.								
THE UTTALLET	odiso koac		Yes 🔯	No			11 125, 46	tune impacting t	ne watered	utoc.				
If a Watercou	rse was Im	pacted, Descri	be Fully.	k				<u> </u>						
			·					···						
	Describe Cause of Problem and Remedial Action Taken.* A 3" steel water line from the discharge side of the 3 phase separator broke causing 100 bbls of produced water to leak onto the ground. 70 bbls were													
		ick. The well				toi Dioki	causing 100	o pots of bioduced	i water to le	ak unt	ine ground,	. 70 ddis we		
D-a-vila Aus	A CC at a d	and Cleanup A	-4' T-1	4										
					water li	ne from	the discharge	side of the 3 pha	ise separato	r broke	causing 100	bbls of proc	luced	
water to leak	onto the gr	ound. 70 bbis	were reco	vered via v	acuum	truck.	The well is g	oing to be plugge	d. Remedia	ition wi	ill be perfor	ned in accord	lance	
with an OCD and BLM approved remediation plan,														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and														
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability														
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, MMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
or the environment. In addition, MMOON acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and or regulations.														
roctoral, state,	or room ray	The same of the sa	Ide. TO IS		<u> </u>			OIL CONS	SERVAT	TON	DIVISIO)N		
Signature:								1	<u> </u>	1011	<u></u>	<u></u>		
DIRHUME.	-U						Annroyad by	District Supervise	>r·			i		
Printed Name	: Christo	pher Jones		<u> </u>		Approved by District Supervisor: Signed By Mile Deministra								
Title: HES	Specialist				A	Approval Date: Expiration Date:								
E-mail Addre	ss: Chris	topher_Jones(@oxy.con	1		1	Conditions of	Approval	כם פייום (ς,	Attached			
Date: 1/1	7/13		(575) 62	28-412	1	Remediation per OCD Rule &								
Attach Addit		ets If Necessa	Phone:				Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 2RP-1522							
		:					Fold.	23. Q	013	•	~r	0 10		
					1		 							

Bratcher, Mike, EMNRD

From:

Kathy Purvis < kathy@bbcinternational.com>

Sent:

Thursday, January 17, 2013 12:59 PM

To: Cc: Bratcher, Mike, EMNRD; jamos@blm.gov; tgregsto@blm.gov christopher_jones@oxy.com; cbrunson@bbcinternational.com;

kswinney@bbcinternational.com; jgilkey@bbcinternational.com

Subject:

Initial C-141 for Old Ranch Knoll 8-6

Attachments:

Initial C-141, signed and sent 1-17-13.pdf

Attached is the initial C-141 for a leak occurring on the Old Ranch Knoll 8 Federal #6 on 1/15/13 in Eddy County, NM. Receipt notification via email is greatly appreciated. Please contact me if you have any questions.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240

Phone: (575) 397-6388 Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From:

Christopher Jones@oxy.com

Sent:

Wednesday, January 16, 2013 7:20 AM

To: Cc: Bratcher, Mike, EMNRD; jamos@blm.gov; Terry_Gregston@blm.gov cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

kathy@bbcinternational.com

Subject:

Old Ranch Knoll 8-6

This is to inform you that Oxy Permian Primary had a spill of produced water at the Old Ranch Knoll 8-6 on January 15, 2013. Oxy released 100 bbls of produced water, 70 bbls was recovered. Leak was due to a 3 INCH STEEL WATER LINE FROM DISCHARGE SIDE OF 3 PHASE SEPARATOR, THE WELL IS GOING TO BE PLUGGED. Oxy will have BBC do some initial remediation, a C-141 to follow. BBC will delineate at a later date.

REGULATORY LEASE # API 30-015-32295

SECT 8 T22S R24E

EDDY COUNTY NEW MEXICO

WEATHER COLD

NORTH ON 285 TO 137 TO MILE MARKER 42, TURN AT OXY SIGN GO 1.5 MILES, TURN LEFT AT BATTERY GO UP HILL .5 MILE, LOCATION ON RIGHT

Chris Jones HES Specialist Permian Primary Production Carlsbad, NM Cell 575-499-3337 Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle