District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

Form C-141 Revised August 8, 2011

JAN 03 2013

Submit I Copy to appropriate District Office in NMOCD ARTESIA

Revised August 8, 2011

Release Notification and Corrective Action												
Name of Company Apache Corporation 873						OPERATOR OPERATOR			Initia	al Report		Final Report
Name of Co Address PC			873	Contact Natalie Gladden								
Facility Nan			st well #1)	Telephone No. 575-390-4186 Facility Type Production Facility								
		- Julian Dallo										
Surface Own	ner BLM			Minera	il Owne	BLM API No. 30-015-30382						
						ON OF RE	LEASE				<u> </u>	
Unit Letter	Section	Township	Range	Feet from th	e Nor	th/South Line	Feet from the	East/We	est Line	County		
Lot 4	-18	17S	31E	990'	FSL		330'	FWL		Eddy		
Latitude						Longitude						
NATURE OF RELEASE												
Type of Relea	ase Oil			Volume of Release 35 Volume Recovered 30								
Source of Rel		r Tank			Date and Hour of Occurrence D				covery			
Was Immediate Notice Given?							11/24/12 Same					
			No 🗌 No									
By Whom? Natalie Gladden						Date and Hour 11/26/2012 612am						
Was a Watero	course Reac	hed?	1 No	If YES, Volume Impacting the Watercourse.								
☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.*												
II a Watercou	rse was Im	pacted, Descri	ibe Fully.									
				1								
Describe Cau												
The transmitter that operates the SWD pumps failed. The pumps did not kick on which high leveled the water tank, which caused the water to go into the												
oil tank. Fluid was recovered from inside the bermed area.												
Describe Are	a Affected a	and Cleanup A	Action Tal	cen.*	···					<u></u>		
				elines to closu	re.							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health	or the envir	ronment. The	acceptano	ce of a C-141	report by	the NMOCD m	arked as "Final R	eport" doc	es not reli	eve the oper	ator of	liability
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state,				nance of a C-1	41 repor	does not reflev	e me operator of i	responsibi	mty for co	этприапсе w	ıcn any	otner
		•	-	OIL CONSERVATION DIVISION								
Signature: Athle (Radole												
						Approved by Environmental Specialist: Signed By Mile Benedical						
Printed Name: Natalie Gladden						1	AN 03 201		75110 W D			
Title: Sr. Env	vironmental	Tech				Approval Da		Ex	piration l	Date:		
E-mail Address: natalie.gladden@apachecorp.com						Conditions of	Conditions of Approval:					
										Attached	Ц	
Date: 12/26/ Attach Addit		Phone: 57	86	Remediation per OCD Rules & ARR 1/77								
A THUCH AUUR	Jonai Siice		ui y			Guidelines. SUBMIT REMEDIATION 2RP-1477						

February 3rd

Bratcher, Mike, EMNRD

From:

Gladden, Natalie < Natalie. Gladden@apachecorp.com>

Sent:

Monday, November 26, 2012 6:12 AM

To:

Bratcher, Mike, EMNRD; Amos, James A (jamos@blm.gov)

Cc:

Bruce Baker (bbaker@rice-ecs.com); Hack Conder <hconder@rice-ecs.com>

Subject:

Attachments:

Tony Federal Battery and Lusk 34 Fed 1H Lusk 34 Fed 1H is in Dist I Internal Release Tony Federal Battery.docx; Lusk 34 Federal 1H Spill_Report

11-21-12.docx

Please review the attached for information concerning the above mentioned releases.

Thanks and if you have any questions please feel free to contact me. I will send your reports shortly.

Natalie Gladden

Apache Corporation

Sr. Environmental Tech

New Mexico District

Cell: 575-390-4186

Office: 575-394-1503 x 1258

Fax: 575-394-2425

Email: natalie.gladden@apachecorp.com



Internal Incident Report - Spill/Release

Location: Tony Federal Battery

Production Area: Hobbs/Loco Hills

District: Eunice

Production Foreman: Travis Carnes

Pumper: Kevin Silco

Date: 11/24/2012

Time: 7am

One Line Summary: Equipment failure

Full summary: The transmitter that operates the SWD pumps failed. The pumps did not kick on which high leveled the water tank, which caused the water to go into the oil tank. Approximately 35bbls of oil was released inside the bermed facility. Approximately 30bbls of oil was recovered.

Remediation Plan: Site will be assessed on 11/26/12 and a work plan will be submitted.

Root cause of incident:

Transmitter failure

Corrective Actions:

- Pumps were turned on hand to lower the water tank level
- Replaced the transmitter

Reported by: Natalie Gladden (575-390-4186)









