


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

0JMW1306548/82

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chevron USA 4323	Contact: Bradley Blevins
Address: P.O. Box 190, Hobbs, NM 88240	Telephone No.: (575) 391-1462 ext. 86424
Facility Name: Ross Ranch 6 Federal #1H	Facility Type: Pipeline

Surface Owner: BLM	Mineral Owner:	API No.: 30-015-36883
--------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	6	26S	30E	350	South	1880	East	Eddy

Latitude: N 32° 03' 55.15" Longitude: W 103° 55' 08.57"

NATURE OF RELEASE

Type of Release: Water and Oil	Volume of Release: 7.21 bbls	Volume Recovered: 0 bbls
Source of Release: open ended line	Date and Hour of Occurrence: 2/24/13 @ 1300 hrs	Date and Hour of Discovery: 2/24/13 @ 1300 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, EMNRD; Jim Amos, BLM	
By Whom? Bradley Blevins	Date and Hour: 2/24/13 @ 1728 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

Depth to water: ~160 ft

If a Watercourse was Impacted, Describe Fully:

Describe Cause of Problem and Remedial Action Taken.* Release was caused by an open ended line. Approximately 6.71 bbls of water and 0.50 bbls of oil were released with 0 bbls recovered. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area.

Describe Area Affected and Cleanup Action Taken.* Visibly stained soil was excavated and hauled away for disposal at a state approved facility. Soil samples were collected and submitted to Cardinal Laboratories for testing. Upon receiving acceptable results and NMOC D approval, the affected area will be backfilled, and returned to proper conditions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by District Supervisor:	
Title: HE Specialist		Approval Date: MAR 06 2013 Expiration Date:	
E-mail Address: bradley.blevins@chevron.com		Conditions of Approval:	
Date: 3-4-13 Phone: (575) 391-1462 ext. 86424		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

April 6, 2013

2RP-1576

Bratcher, Mike, EMNRD

From: Blevins, Bradley G <Bradley.Blevins@chevron.com>
Sent: Monday, March 04, 2013 8:25 AM
To: Bratcher, Mike, EMNRD; 'James Amos - Bureau of Land Management (jamos@blm.gov)'
Cc: Blevins, Bradley G
Subject: ROSS RANCH 6 FEDERAL 1H- Initial C-141
Attachments: [Untitled].pdf

Mike/ Jim

Please find the attached C-141 for the release we had on the Ross Ranch 6 Federal 1H, We currently have a environmental crew working on this cleanup. Once we receive sample data I will contact you for a meeting t discuss. If you have any questions please give me a call or email.

Thanks

Bradley Blevins
Chevron Delaware Basin
HE Specialist
Hobbs FMT
Direct 575-391-1462 86424
Cell- 575-441-0341

Bratcher, Mike, EMNRD

From: Blevins, Bradley G <Bradley.Blevins@chevron.com>
Sent: Sunday, February 24, 2013 5:29 PM
To: Bratcher, Mike, EMNRD; 'James Amos - Bureau of Land Management (jamos@blm.gov)'
Cc: Blevins, Bradley G; 'Daniel Dominguez'; 'Roger Boone'
Subject: Ross Ranch 6 Federal 1H

Jim/ Mike

Chevron had a release on the above referenced location, 6.71 barrels of water and 0.50 barrels of oil was released outside containment. The fluid ran off the west side of the well pad into the pasture. I will have a environmental crew on location Monday morning. I will follow up with initial C-141, if you have any question please let me know.

Thanks,

Bradley Blevins
Chevron Delaware Basin
HE Specialist
Hobbs FMT
Direct 575-391-1462 86424
Cell- 575-441-0341