


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JM 1306550350 OPERATOR ☒ Initial Report ☒ Final Report

| | | | |
|-----------------------|---|---------------|-------------------------------|
| Name of Company | COG OPERATING LLC 229137 | Contact | Pat Ellis |
| Address | 600 West Illinois Avenue, Midland, TX 79701 | Telephone No. | 432-230-0077 |
| Facility Name | DODD FEDERAL UNIT #15A | Facility Type | TANK BATTERY |
| Surface Owner FEDERAL | | Mineral Owner | Lease No. (API#) 30-015-35139 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| P | 15 | 17S | 29E | | | | | EDDY |

Latitude 32.82827

Longitude 104.05744

NATURE OF RELEASE

| | | | | | |
|--|---|---|--|-----------------------------------|-------------------|
| Type of Release | Oil | Volume of Release | 100bbls | Volume Recovered | 99bbls |
| Source of Release | Open valve on tank | Date and Hour of Occurrence | 02-24-2013 | Date and Hour of Discovery | 02-24-2013 6:55am |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Jim Amos - BLM / Mike Bratcher - NMOCD | | |
| By Whom? | Michelle Mullins | Date and Hour | 02-25-2013 9:17am | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |
| If a Watercourse was Impacted, Describe Fully.* | | | | | |
| Describe Cause of Problem and Remedial Action Taken.* | | | | | |
| Due to a closed equalizer line the oil tank at the facility overflowed. We have opened the equalizer line to prevent reoccurrence. | | | | | |
| Describe Area Affected and Cleanup Action Taken.* | | | | | |
| Initially 100bbls of oil were released from the oil tank inside the tank battery due to a closed equalizing line. We were able to recover 99bbls of oil with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition. | | | | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | | | | |
| Signature:  | | OIL CONSERVATION DIVISION | | | |
| Printed Name: Josh Russo | | Approved by District Supervisor: | | Accepted for record NMOCD | |
| Title: Senior Environmental Coordinator | | Approval Date: MAR 06 2013 | | Expiration Date: | |
| E-mail Address: jrusso@concho.com | | Conditions of Approval: | | Attached <input type="checkbox"/> | |
| Date: 03-04-2013 Phone: 432-212-2399 | | | | | |

* Attach Additional Sheets If Necessary

22P-1577

Accepted for record
NMOCD

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Tuesday, March 05, 2013 12:36 PM
To: Amos, James; Bratcher, Mike, EMNRD
Cc: Joshua Russo
Subject: C-141 Initial/Finial - Report DODD FEDERAL UNIT #15A TANK BATTERY
Attachments: DODD FEDERAL UNIT #15A TANK BATTERY -- DATE OF RELEASE -- 02-24-2013.pdf

Gentlemen,

Please see attached a C-141 Initial/Finial Report for a release that occurred at our DODD FEDERAL UNIT #15A TANK BATTERY on 02-24-2013 in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Monday, February 25, 2013 8:17 AM
To: Bratcher, Mike, EMNRD; 'jamos@blm.gov'
Cc: Joshua Russo; Robert Grubbs
Subject: Dodd Federal 15A-Immediate Notification

Mr. Bratcher, Mr. Amos:

At approximately 7:00 a.m. on 02/24/2013, a produced fluid release was discovered at the above-referenced location. An estimated 100 bbls of produced fluid was released. The fluid was contained inside a 40 mil lined facility. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

32 49.680 104 03.470

Dodd Federal 15A

Unit P

Section 15 T17S R29E

NMLC-028731A

Eddy County, NM

Off Highway 82, turn north onto Barnaval Draw Road. Take first road east. Travel approximately 2 miles, turn west into location.

Michelle Mullins

HSE Field Tech

2407 Pecos Avenue

P.O. Box 1630

Artesia, NM 88211-1630

Phone: (575)746-2010

Cell: (432) 934-1052

mmullins@conchoresources.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.