

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico
Energy Minerals and Natural Resources

MAR 07 2013

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

| | | | |
|-----------------|----------------------------------|---------------|-----------------|
| Name of Company | McDonnold Operating Inc. | Contact | Craig McDonnold |
| Address | 505 N. Big Spring Suite 204 | Telephone No. | 432-682-3499 |
| Facility Name | Langlie Jack Unit 2 M. and T. M. | Facility Type | operator |
| Surface Owner | | Mineral Owner | |
| | | API No. | 30-025-11169 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North South Line | Feet from the | East West Line | County |
| O | 20 | 24 S | 37 E | 660 | | 1980 | | Lea |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|-----------------|----------------------------|---------|
| Type of Release | Produced Water | Volume of Release | 410 Bbls | Volume Recovered | 35 Bbls |
| Source of Release | Langlie Jack Unit #14 | Date and Hour of Occurrence | | Date and Hour of Discovery | 3/3/13 |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Geoffrey LeKing | | |
| By Whom? | Ken Rogers | Date and Hour | 3-5-13 | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



INJ Line Leak. Call VAC Truck + Pickup standing water. Made ONE call.
Fence in Area. dug out Leak + Repair Leak - Left open.

Describe Area Affected and Cleanup Action Taken.*

50' East of #14 wellbore.

Notified OCD for recommended Action.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|-----------------|---|--------------------------------------|---|
| Signature: |  | OIL CONSERVATION DIVISION | |
| Printed Name: | Craig M. McDonnold | Approved by Environmental Specialist |  |
| Title: | President | Approval Date: | 3-07-13 |
| E-mail Address: | Craig@McDonnold.net | Expiration Date: | 5-07-13 |
| Date: | 3/5/13 | Conditions of Approval: | DELINQUENT & REMEDIATE PER NMOCD RULES. |
| Phone: | 432-682-3499 | Attached | <input type="checkbox"/> |

* Attach Additional Sheets If Necessary

SUBMIT FINAL C-141 BY

IRP-5-13-2916