

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

MAY 08 2013

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company OXY PERMIAN	Contact TONY AGUILAR
Address 1017 W. STANOLIND ROAD	Telephone No. 575-397-8251
Facility Name NORTH HOBBS UNIT SATELLITE 32W	Facility Type INJECTION HEADER

Surface Owner OXY	Mineral Owner OXY PERMIAN	Lease No.
-------------------	---------------------------	-----------

LOCATION OF RELEASE

NEAREST WELL: STATE LAND SECTION 32 #009
APL # 30.025.23309

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	32	18	38					LEA

Latitude 32.4203.73 Longitude 103.1020.57

NATURE OF RELEASE

Type of Release PRODUCE WATER	Volume of Release 250 BBLs	Volume Recovered 70 BBLs
Source of Release 3" STEEL ZAPLOCK FLOWLINE	Date and Hour of Occurrence 4/30/2013 7:30:00 AM	Date and Hour of Discovery 4-30-2013 7:30AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? GEOF LEKING	
By Whom? TONY AGUILAR	Date and Hour 4-30-13 9:10AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
EXTERNAL AND POSSIBLE END OF LIFE, CAUSING ABOUT 250 BBLs OF PRODUCE WATER AND SOME SATURATION ON GROUND.

Describe Area Affected and Cleanup Action Taken.*
EAST SIDE OF SATELLITE FACILITY AND SOME ON THE OUT SIDE OF FENCE ON THE NORTH/EAST SIDE OF FACILITY. STANDING WATER WAS PICKED UP, CALLED TO HAVE LINE REPAIRED OR REPLACED. AFTER REPAIRS, WILL BE TURNED OVER TO ENVIRONMENTAL DEPARTMENT FOR CLEANUP.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Aguilar</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: TONY AGUILAR	<i>Geoffrey LeKing</i> Approved by District Supervisor Environmental Specialist	
Title: <i>HES Specialist</i>	Approval Date: <i>05/09/13</i>	Expiration Date: <i>07/09/13</i>
E-mail Address: RAYMOND_AGUILAR@OXY.COM	Conditions of Approval: <i>SUBMIT FINAL</i>	
Date: <i>5-1-13</i> Phone: 575-397-8251	<i>C-141 BY 07/09/13</i>	Attached <input type="checkbox"/> <i>IRP-5-13-2917</i>

* Attach Additional Sheets If Necessary

MAY 20 2013