


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

JMN 1316554192

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	PINTO 36 STATE COM #004H	Facility Type	TANK BATTERY

Surface Owner	STATE	Mineral Owner		Lease No. (API#)	30-015-40058
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	18S	25E					EDDY

Latitude 32.69766

Longitude 104.43324

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	3bbls of oil 12bbls of produced water	Volume Recovered	3bbls of oil 11bbls of produced water
Source of Release	Hole in 4" production line	Date and Hour of Occurrence	06-01-2013	Date and Hour of Discovery	06-01-2013 12:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



A hole in the bottom of a 4" production occurred due to corrosion. The line has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially 3bbls oil and 12bbls of produced water were released to a corroded 4" line. We were able to recover 3bbls of oil and 11bbls of produced water with a vacuum truck. The entire release was contained inside the lined facility. All free fluids have been recovered. Any contaminated gravel has been removed, the liner has been washed, and we have replaced with clean gravel as necessary. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor		Signed By	
Printed Name:	Robert Grubbs Jr.	Approval Date:		JUN 14 2013	
Title:	Senior Environmental Coordinator	Expiration Date:			
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>	
Date:	06-05-2013	Phone:		432-661-6601	

* Attach Additional Sheets If Necessary

2RP-1681

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, June 06, 2013 3:23 PM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo
Subject: C-141 Initial Report - Pinto 36 State Com #004H
Attachments: PINTO 36 STATE COM #004H (TANK BATTERY) -- DATE OF RELEASE -- 06-01-2013.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 06-01-2013 at our Pinto 36 State Com #004H (Tank Battery) in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Friday, June 07, 2013 6:25 AM
To: Bratcher, Mike, EMNRD
Subject: RE: C-141 Initial Report - Pinto 36 State Com #004H

Mr. Bratcher,

The C-141 that I had sent you yesterday the 7th of June, 2013 I had mislabeled the C-141. I put Initial Report - Pinto 36 State Com #004H when it is Initial/Final Report - Pinto 36 State Com #004H. Sorry for the inconvenience hope you have a good weekend.

Thanks,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



From: Robert Grubbs
Sent: Thursday, June 06, 2013 4:23 PM
To: Mike Bratcher (mike.bratcher@state.nm.us) (mike.bratcher@state.nm.us)
Cc: Joshua Russo
Subject: C-141 Initial Report - Pinto 36 State Com #004H

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 06-01-2013 at our Pinto 36 State Com #004H (Tank Battery) in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.