


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

JM 1318429370

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company: Chevron USA	4323	Contact: Amy Barnhill
Address: 2401 Avenue O Eunice, NM 88231		Telephone No.: 432-940-8524
Facility Name: Bogle Flats #18		Facility Type: Tank Battery

Surface Owner: State of NM	Mineral Owner: State of NM	API No. 30-015-28884
----------------------------	----------------------------	----------------------

LOCATION OF RELEASE

Unit Letter G-SW/4 of NE/4	Section 16	Township 22S	Range 23E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
----------------------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 322339.40 Longitude 1043609.76

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 22 Bbls	Volume Recovered: 20 Bbls
Source of Release	Date and Hour of Occurrence: 6-10-2013 - 12:00pm	Date and Hour of Discovery 6-10-2013 - 7pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (575) 748-1283 x 108	
By Whom? Amy Barnhill	Date and Hour: 6-11-2013 - 8:42am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

There was a leak under a tank. The additional weight of the fluid evidently forced open a bad spot and we lost the fluid in the berm.

Describe Area Affected and Cleanup Action Taken.*

Spill inside the berm. Nabors trucking picked up 20 Bbls of fluid. Gator PW/Oil absorbent was spread over affected area.

Further remediation will be performed in accordance with a NMOCD approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Amy Barnhill

Printed Name: Amy Barnhill

Title: HE Specialist

E-mail Address: ABarnhill@chevron.com

Date: 6-21-2013

Phone: 432-940-8524

Approved by Environmental Specialist:

Signed By

Mike Bratcher

JUL 03 2013

Approval Date:

Expiration Date:

Conditions of Approval:
Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION**

Attached ☐

PROPOSAL NO LATER THAN:

August 3rd 2013

2RP-1701

* Attach Additional Sheets If Necessary


Bratcher, Mike, EMNRD

From: Barnhill, Amy D. <ABarnhill@chevron.com>
Sent: Tuesday, June 25, 2013 8:06 AM
To: Bratcher, Mike, EMNRD
Subject: Paperwork on Boggle Flats 18 PW Spill
Attachments: Boggle Flats #18.doc

Please let me know if I need to do anything else.

Thank you,
Amy Barnhill, CBES
Health and Environment Specialist
MCBU Midland/Delaware Basin
Big Lake, Conger, Eunice, Ft. Stockton
Cell: 432-940-8524
E-Mail: ABarnhill@chevron.com

"The highest performance you can expect is the lowest standard you set"



CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email.


Bratcher, Mike, EMNRD

From: Barnhill, Amy D. <ABarnhill@chevron.com>
Sent: Tuesday, June 11, 2013 7:42 AM
To: Bratcher, Mike, EMNRD
Cc: Barnhill, Amy D.
Subject: 20 BBL PW Spill

Chevron had a 20 Bbl Produced Water Spill at the Bogle Flats battery in Carlsbad yesterday. I will fill out the proper paperwork with details and get it submitted to you. Please let me know if you need further information.

Thank you,
Amy Barnhill, CBES
Health and Environment Specialist
MCBU Midland/Delaware Basin
Big Lake, Conger, Eunice, Ft. Stockton
Cell: 432-940-8524
E-Mail: ABarnhill@chevron.com

"The highest performance you can expect is the lowest standard you set!"



CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email.

Warren, JeanMarie, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Wednesday, June 26, 2013 7:57 AM
To: Barnhill, Amy D.
Cc: Warren, JeanMarie, EMNRD
Subject: RE: Paperwork on Boggle Flats 18 PW Spill

Amy,

The C-141 submitted is marked "Final Report". In the body of the document, it is stated that remediation will be performed in accordance with a NMOCD approved remediation plan. Where remedial action is to be performed, I can only accept this C-141 as an "Initial Report". No need to resubmit, I can work with this one.

If you have any questions or concerns, please contact me.


Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Barnhill, Amy D. [<mailto:ABarnhill@chevron.com>]
Sent: Tuesday, June 25, 2013 8:06 AM
To: Bratcher, Mike, EMNRD
Subject: Paperwork on Boggle Flats 18 PW Spill

Please let me know if I need to do anything else.

Thank you,
Amy Barnhill, CBES
Health and Environment Specialist
MCBU Midland/Delaware Basin
Big Lake, Conger, Eunice, Ft. Stockton
Cell: 432-940-8524
E-Mail: ABarnhill@chevron.com

"The highest performance you can expect is the lowest standard you set"



CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email.

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Wednesday, June 26, 2013 7:57 AM
To: 'Barnhill, Amy D.'
Cc: Warren, JeanMarie, EMNRD
Subject: RE: Paperwork on Boggle Flats 18 PW Spill

Amy,

The C-141 submitted is marked "Final Report". In the body of the document, it is stated that remediation will be performed in accordance with a NMOCD approved remediation plan. Where remedial action is to be performed, I can only accept this C-141 as an "Initial Report". No need to resubmit, I can work with this one.

If you have any questions or concerns, please contact me.


Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Barnhill, Amy D. [<mailto:ABarnhill@chevron.com>]
Sent: Tuesday, June 25, 2013 8:06 AM
To: Bratcher, Mike, EMNRD
Subject: Paperwork on Boggle Flats 18 PW Spill

Please let me know if I need to do anything else.

Thank you,
Amy Barnhill, CBES
Health and Environment Specialist
MCBU Midland/Delaware Basin
Big Lake, Conger, Eunice, Ft. Stockton
Cell: 432-940-8524
E-Mail: ABarnhill@chevron.com

"The highest performance you can expect is the lowest standard you set"



CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email.

