<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District III

District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources JUL 1 1 2013

RECEIVED

Form C-141 Revised October 10, 2003

NMOGENT PROPY & appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Santa 1 0, 1111 07303											
Release Notification and Corrective Action OPERATOR Initial Report Final Report											
MMLn	1319	7360	64	_	OPERA	ΓOR					
Name of Co	mpany: Li	nn Operating	g 20	09324	Contact: Ga	Contact: Gary Wink					
Address: 21	30 W. Ber	nder Hobbs	, NM 882	240	Telephone N	Telephone No.: 575738-1739					
Facility Nan	ne: Skelly	B Battery Sa	atelite # 5	- Skelly 276	Facility Typ	Facility Type: Satelite					
Surface Ow	ner: Feder	al		Mineral C	Owner: Federal		API No	API No.: 3001529225			
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County			
D	27	178	31E	687	North	1183	West	Edo	ly		
					<u>. </u>	-	J	<u> </u>			

		- 7.5		007	1	101111	1100				
Latitude: 32.8109503533785 Longitude: -103.862221362993											
NATURE OF RELEASE											
Type of Rele	ase: Produc	ed Water / Oil			Volume of Release: 3bbls / 2bbls Volume Recovered: 0 / 0						
Source of Release: Poly pipeline						Date and Hour of Occurrence: Date and Hour of Discovery:					
The second of th						06/17/2013 1:00pm 06/17/2013 1:00pm					
Was Immediate Notice Given?						If YES, To Whom?					
☐ Yes ☐ No ☐ Not Required						M. Bratcher - NM OCD Mike Burton-BLM					
By Whom? (Date and Hour 07/11/2013 3:50pm					
Was a Water	course Reac	hed?				If YES, Vo	lume Impacting	the Water	course.		
☐ Yes ☒ No											
If a Watercourse was Impacted, Describe Fully.*:											
Describe Cause of Problem and Remedial Action Taken.*: Got a phone call from roustabout at about 1:00pm and told me I had a flowline leak. So I went to check it out and I had a leak in the middle of Taylor Draw just south of Skelly Unit #276 walked out the flowline and it went to Satalite #5 transfer pump. Had BSG Roustabout fix the leak and we lost about maybe 5 barrels of fluid total. Cost for the day is about 300 dollars.											
Describe Area Affected and Cleanup Action Taken.*: Impacted area is about 10'X15'.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
Signature: Harry W. Wink						Approved by District Supervisor: Signed By Mily Buseauce					
Printed Name: Gary W. Wink											
Title: Production Foreman							Approval Date: Expiration Date:				
E-mail Addr Date: 07/11/2* Attach Addi	2013		hone: 575	-390-3477	F		f Approval: per OCD Rule by BLM . SUBM			Attached 2RP—1701	

Bratcher, Mike, EMNRD

From:

McCracken, Theresa < TMcCracken@linnenergy.com>

Sent:

Thursday, July 11, 2013 4:03 PM

To:

mburton@blm.gov; Bratcher, Mike, EMNRD

Cc:

Callahan, Terry; Fitzwater, Nancy; Butters, Thomas; Golding, Chris; Ragland, Ron;

Hernandez, Joe; Wink, Gary

Subject:


Linn- Skelly B Battery Satelite # 5 6-17-13

Attachments:

Skelly B Battery Sat# 5 6-17-13.pdf

Importance:

High



Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator LINN Energy, LLC 2130 W Bender Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.