

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

DEC 12 2011

Form C-141
Revised October 10, 2003

NMOCD ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

JMW 1320736571

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	Southern Union Gas Services 34951	Contact	Rose Slade
Address	801 South Loop 464, Monahans, TX 79756	Telephone No.	432-940-5147
Facility Name	California B Extension (2011-10-035)	Facility Type	Natural Gas Pipeline
Surface Owner	State of New Mexico	Mineral Owner	API No 30-025-28822

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	26S	27E					Eddy

Latitude 32 degrees 01.229' Longitude 104 degrees 08.088'

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	40,320 mcf	Volume Recovered	None
Source of Release	16-Inch Steel Pipeline (High Pressure)	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	October 27, 2011
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Release was caused by a 3rd Party failing to issue a line locate request (One Call). A road grader struck the steel pipeline resulting in the release of natural gas. The 3rd Party has been reported New Mexico One Call for failing to issue a one call.

Describe Area Affected and Cleanup Action Taken.*

Pipeline was repaired using 16 feet of 16 inch diameter steel pipe, and placed back in service

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Rose Slade

Title: EHS Compliance Specialist

E-mail Address: rose.slade@sug.com

Date: December 2, 2011

Phone: 432-940-5147

OIL CONSERVATION DIVISION

Approved by District Supervisor: Accepted for record
NMOCD

Approval Date: JUL 26 2013

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

JMW 1320736413
JMW 1320737536

2RP-1751

Bratcher, Mike, EMNRD

From: Stanley, Curt D. [Curt.Stanley@SUG.com]
Sent: Monday, December 12, 2011 8:50 AM
To: Bratcher, Mike, EMNRD
Cc: Slade, Rose; Inskeep, Cyndi M.
Subject: Gas Only C-141's
Attachments: DOC_20111212103238.PDF

Mike,

Attached, please find five (5) NMOCD C-141's for natural gas only releases in NMOCD District 2. If you have any questions, please contact me at your convenience.

Thank you,

Curt Stanley
EHS Compliance Specialist
Southern Union Gas Services, Ltd
801 S. Loop 464
Monahans, Texas 79756
Phone 817.302.9717
Fax 817.302.9701
Cell 575.390.7595
curt.stanley@sug.com

Private and confidential as detailed [here](#). If you cannot access hyperlink, please e-mail sender.