District |
1625 N. French Dr., Hobbs, NM 88240.
District ||
1301 W. Grand Avenue, Artesia, NM 88210
District |||
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr.; Santa Fc, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

| RECEIVED | Form G-141: |
|---------------------|---|
| FEB 0.6 2012 | bed October 10, 2005 |
| NMOCD ARTESIA | ffice in accordance h Rule 116 on back side of form |

| Release Notification and Corrective Action | | |
|--|--|--|
| MM 320756677 | OPERATOR Initial Report Initial Report | |
| Name of Company Southern Union Gas Services 3495/ | Contact Rose Slade | |
| Address 801 S. Loop 464 Monahans, Texas 79756 Telephone No. 432-940-5147 | | |
| Facility Name California B (2011-09-198) Facility Type Natural Gas Pipeline | | |
| Surface Owner, State of New Mexico Mineral Owner API No 30-025-28822 | | |
| LOGATION OF RELEASE | | |
| Unit Letter, Section Township Range Feet from the North/South Line Feet from the East/West Line County M 2 26S 31E | | |
| Latitude 32 degrees 03.896 Longitude 103 degrees 45.172 | | |
| NATURE OF RELEASE | | |
| Type of Release Natural Gas | Volume of Release 600 mcf. Volume Recovered None | |
| Source of Release 16-Inch Steel Pipeline (Low Pressure) | Date and Hour of Occurrence Date and Hour of Discovery Unknown September 15, 2011 | |
| Was Immediate Notice Given? | If YES, To Whom? | |
| □ Yes ☑ No □ Not Require | | |
| ByWhom? | Date and Hour | |
| Was a Water course Reached? □ Yes ☑ No | If YES, Volume Impacting the Watercourse | |
| If a Watercourse was Impacted Describe Fully * | | |
| | | |
| Describe Cause of Problem and Remedial Action Taken. Failure of a segment of the sixteen (16) inch low pressure steel pipeline resulted in the release of natural gas. The pipeline segment was replaced to mitigate the release. | | |
| | | |
| Describe Area Affected and Cleanup Action Taken: | The second secon | |
| Ripeline segment was replaced and placed back in service | | |
| | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger | | |
| public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability | | |
| should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other. | | |
| federal, state, or local laws and/or regulations | 2 E | |
| | OIL CONSERVATION DIVISION | |
| Signature | Accepted for record | |
| | Approved by Environmental Specialist: NMOCD | |
| Printed Name: Rose Slade | Approval Date: Expiration Date: | |
| Title: EHS Compliance Specialist | Approval Date: Expiration Date: | |
| E-mail Address: rose:slade@sug.com. | Conditions of Approval. Attached | |
| Date: December 19, 2011 Phone: 432-940-5147 | | |
| 20 10 10 10 10 10 10 10 10 10 10 10 10 10 | 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1 | |

*Attach Additional Sheets If Necessary, FJMW 1320755846 JJMW 1320756917

2RP-1757

Bratcher, Mike, EMNRD

From:

Inskeep, Cyndi M. [Cyndi.Inskeep@SUG.com]

Sent:

Monday, February 06, 2012 10:49 AM

To:

Bratcher, Mike, EMNRD

Cc:

Slade, Rose

Subject:

C141

Attachments:

Various Sept 2011.pdf

Mr. Bratcher:

You will find attached a C-141 for the following:

California B (4) California A

Thank you,

Cyndi Inskeep

EHS Associate
Southern Union Gas Services
801 S. Loop 464
Monahans TX 79756
email: cyndi.inskeep@suq.com
817-302-9720 phone
432-638-5328 cell
817-302-9701 fax



Private and confidential as detailed here. If you cannot access hyperlink, please e-mail sender.

All (IN)
Paul Let