1020 N. FICHCH DT., FIODDS, INVI 88240	New Mexico and Natural Resources FEB 0 6 2012 Revised October 10, 2003
1301 W. Grand, Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio, Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 Sout	rvation Division h St. Francis Dr. e, NM 87505
Réléasé Notification and Corrective Action   MAW 1321051610 OPERATOR Maine of Company Initial Report Final Report   Name of Company Southern Union Gas Services 34/951 Contact Rose Slade Contact Rose Slade   Address 801'S. Loop 464 Monahans, Texas 79756 Telephone No. 432-940-5147 Facility Name California B (2011-09-186) Facility Type Natural Gas/Pipeline	
Surface Owner   State of New Mexico   Mineral Owner   API No 30-025*23822     LOCATION OF RELEASE   LOCATION OF RELEASE   County   County   County   County   County   Eddy   County   Coun	
Latitude 32 degrees 03 900' Longitude 103 degrees 44 936'	
Type of Release Natural Gas Source of Release 16 Inch Steel Pipeline (Low Pressure) Was Immediate Notice Given?	Volume of Release   390 mcf   Volume Recovered. None.     Date and Hour of Occurrence   Date and Hour of Discovery     Unknown   September 2, 2011     If YES, To Whom?   September 2, 2011
By Whom? Was a Watercourse Reached? Yes X No	Date and Hour If YES, Volume Impacting the Watercourse.
If a Watercourse was Impacted, Describe Fully.*	
*Describe Cause of Problem and Remedial Action Taken: Failure of a segment of the sixteen (16) incluiow pressure steel pipeline resulted in the release of natural gas. The pipeline segment was replaced to mitigate the release.	
Describe Area Affected and Cleanup Action Taken.* Pipeline segment was replaced and placed back in service	
regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by the should their operations have failed to adequately investigate and remedia	the best of my knowledge and understand that pursuant to NMOCD rules and notifications and perform corrective actions for releases which may endanger the NMOCD marked as "Final Report" does not relieve the operator of liability at contamination that pose a threat to ground water, surface water, human health does not relieve the operator of responsibility for compliance with any other
Signature: D > Printed Name: Rose Blade	OIE:CONSERVATION DIVISION Accepted for record Approved by Environmental Specialist: NMOCD
Title:   EHS Compliance Specialist     :E-mail:Address:   rose.slade@sug.com	Approval Date: Conditions of Approval: Attached
Date December 19, 2011 Phone: 432-940-5147 * Attach Additional Sheets If Necessary, FJMW 1321031398 IJMW 1321031900	2RP-1758
IJMW 1321031900	

## Bratcher, Mike, EMNRD

From: Sent: To: Cc: Subject: Attachments: Inskeep, Cyndi M. [Cyndi.Inskeep@SUG.com] Monday, February 06, 2012 10:49 AM Bratcher, Mike, EMNRD Slade, Rose C141 Various Sept 2011.pdf

All Criss Davel p. E. P.

Mr. Bratcher:

You will find attached a C-141 for the following:

California B (4) California A

Thank you,

Cyndi Inskeep

EHS Associate Southern Union Gas Services 801 S. Loop 464 Monahans TX 79756 email: <u>cyndi.inskeep@suq.com</u> 817-302-9720 phone 432-638-5328 cell 817-302-9701 fax



Private and confidential as detailed here. If you cannot access hyperlink, please e-mail sender.