


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1321040276

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services, L.L.C. 100347	Contact	Dina Babinski
Address	Env. Dept. PO Box 4324, Houston, TX 77210-4324	Telephone No.	210-232-4880
Facility Name	Gathering Lines, Eddy County #1	Facility Type	Gathering Pipeline
Surface Owner-	several, pipeline leak	Mineral Owner -	several, pipeline leak
		Lease No.	N/A


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	32	20S	26E					Eddy

Latitude N32.5243 Longitude W-104.4020

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	8.5 MMscf	Volume Recovered	0
Source of Release	Pipeline	Date and Hour of Occurrence	7-27-2011, 20:40 (Mountain Time)	Date and Hour of Discovery	7-27-2011, 20:40 (Mountain Time)
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD		
By Whom?	Dina Babinski	Date and Hour	7/29/2011, 07:43		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken Technician discovered release location and later confirmed to be on Enterprise Pipeline. Leak is on lateral B-6, 10" line, about 36,960 ft. of line will be shut in, line will be LO/TO and blown down. Leak is located in T-20S, R-26E and Section 32 in Carlsbad N.M. in Eddy county, no report of fire, no injuries and no fluid on ground due to leak.					
Describe Area Affected and Cleanup Action Taken. A standard one-call will be initiated to expedite repairs next week. Producers were notified of shut in, there were seven wells shut in due to leak, approximately 7 miles of pipeline will be blown down. Estimated gas loss 8.5 MMscf, anticipated gas loss due to pipeline blow down to perform safe repairs, 630 Mscf.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Carson Dina Babinski	Approved by District Supervisor:	Accepted for record NMOCD
Title: Senior Environmental Scientist	Approval Date: JUL 29 2013	Expiration Date:
E-mail Address: djbabinski@eprod.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/28/11	Phone: 210-232-4880	

* Attach Additional Sheets If Necessary

fJMW 1321039948

iJMW 1321040820

2RP-1764

Bratcher, Mike, EMNRD

From: Babinski, Dina [DJBabinski@eprod.com]
Sent: Thursday, July 28, 2011 3:19 PM
To: Bratcher, Mike, EMNRD
Cc: Nolan, Shiver; Thompson, Roger
Subject: Fw: Scan from a Xerox WorkCentre
Attachments: img-728161258-0001.pdf

Mike, I realized the signature was missing on the previous email. This should be better, sorry about that.

Dina

----- Original Message -----

From: Xerox CentreWare Print Admin
Sent: Thursday, July 28, 2011 04:12 PM
To: Babinski, Dina
Subject: Scan from a Xerox WorkCentre

Please open the attached document. It was scanned and sent to you using a Xerox WorkCentre.

Number of Images: 1
Attachment File Type: PDF

Device Name: WorkCentre 7335
Device Location:

For more information on Xerox products and solutions, please visit <http://www.xerox.com/>

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.

Bratcher, Mike, EMNRD

From: Babinski, Dina [DJBabinski@eprod.com]
Sent: Thursday, July 28, 2011 1:00 PM
To: Bratcher, Mike, EMNRD
Cc: Thompson, Roger; Nolan, Shiver
Subject: 072711 line leak
Attachments: 072711 leak.DOC; Babinski Dina.vcf

Mike, attached is the C-141 for the leak discovered yesterday. Also, I've attached my contact information in case you have any questions. Nice to visit with you this morning, maybe we'll have an opportunity to meet someday.

Dina Babinski
Sr Environmental Scientist
Enterprise Products Operating, LLC
(210) 528-3824 (office)
(210) 232-4880 (mobile)
(713) 803-9442 (fax)
DJBabinski@eprod.com

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.