District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210\* District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

高端1000億7%

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505


Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action													
	MMIn	NMW 1321240480						ГOR		☐ Initial Report ☐ Final Report			
	Name of Co	Name of Company Enterprise Field Services LLC PO Box 4324, Houston, TX 77252						Contact Jim Heap					
	Facility Nar		O Box 4324 Sipeline ROV				Telephone No. 432-686-5404 Facility Type: Gas Gathering Pipeline						
	Surface Ow	ner N	Aultiple Owr	iers	Mineral C								
	Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County												
	Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/	West Line	County   Eddy		
		4	21S	26E					<u> </u>	<del> </del>			
Latitude 32.510167 N Longitude -104.299201 W													
NATURE OF RELEASE													
	Type of Relea						Release 193 MC		Volume Recovered 0				
	Source of Release Pipeline Leak						ſ	lour of Occurrenc 01-2013 17:00 (M	- :	Date and Hour of Discovery 02-05-2013 15:00 (MST)			
	Was Immedia	ate Notice (		Yes 🗌	No ⊠ Not Re	equired	If YES, To						
	By Whom?				710 23 710110		Date and Hour						
	Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
	☐ Yes ⊠ No							ì		RECI	EIVED		
	If a Watercou	rse was Im			<u> </u>								
										FEB 1	<b>1 1</b> 2013		
	restruments, abrimats, at Marian							\ \	MOCD	ARTES!A			
it.e.	Describe Cause of Problem and Remedial Action Taken.*												
	A second perforation was discovered during a full-line inspection related to the repair effort of the previously reported release sent under separate cover on February 4, 2013.												
	Describe Area	Describe Area Affected and Cleanup Action Taken.*											
·													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
	regulations all	l operators:	are required to	report an	d/or file certain re	elease no	tifications an	d perform correct	ive acti	ons for rele	ases which may	endanger	
	regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
	or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											ny other	
	federal, state,	or local law	vs and/or regu	lations.	·	OII COM				SERVATION DIVISION			
	0.	11						OIL CONSERVATION DIVISION					
ł	Signature:  Printed Name: Matthew E. Marra						mmouad he. I	District Communica		supplied for record			
							Approved by District Supervisor:			NMOCD			
	Title: S	enior Direc	tor, Environm		A	pproval Date	UL 3 1 2013		Expiration Date:				
	E-mail Address: memarra@eprod.com  Date: 2 - 7 - 2013 Phone: 713-381-6684  Attach Additional Speets If Necessary						onditions of Approval:		1	Attached			
									1				
*	Attach Additi	onal Shee	ts If Necessa	- <u>381-0084</u> Iry								06	
FTMW 1321240155 2RP-1785													
	7117	· CAA I	J - 1 -	. 🔾					:		• • •		

iJMW 1321241058





February 7, 2013

7012 2210 0001 2197 2692 Return Receipt Requested

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE:

Form C-141 Report

Gas Loss Reported in the Carlsbad Gathering Field

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the following release found on our B6 Gathering Line in our Carlsbad Gathering Field, Eddy County.

The release was discovered during a full-line inspection associated with the repair of a previously reported leak and blow-down on the same line.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Matthew E. Marra

Senior Director, Environmental

/sjn

attachments