

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1321956821

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services LLC 1000347	Contact	Jim Heap
	PO Box 4324, Houston, TX 77252	Telephone No.	432-686-5404
Facility Name	Pipeline ROW, D-1 Line (Colt Fed #2)	Facility Type:	Gas-gathering Pipeline

Surface Owner	Mineral Owner	NA	Lease No.	NA
---------------	---------------	----	-----------	----

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	18	18S	29E					Eddy

Latitude: N 32° 44.7050 Longitude: W 104° 6.9494

NATURE OF RELEASE

Type of Release	Natural Gas /	Volume of Release	488 MCF	Volume Recovered	0
Source of Release	Pipeline Blow-down to relieve hydrate blockage.	Date and Hour of Occurrence (Start)	01-24-2012 12:20 hrs	Date and Hour of Discovery	01-24-2012 12:00 hrs
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

FEB 01 2012

Describe Cause of Problem and Remedial Action Taken.*

The affected section of the 6-inch line was isolated and blown-down to relieve a hydrate blockage.

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Matthew E. Marra

Title: Senior Director, Environmental & Technical Service

E-mail Address: memarra@eprod.com

Date: Phone: 432-686-5404

Approved by District Supervisor:

AUG 07 2013

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

FJMW 1321956380

iJMW 1321957016


2RP-1800



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

January 30, 2012



7011 1150 0002 0385 9722
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Products Operating LLC
Line D-1 Maintenance Blow-down.**


Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC, please find the requisite C-141 Form for our D-1 Line maintenance blow-down. The blow-down was performed to relieve a hydrate build-up and blockage causing an over pressure situation in the pipeline.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Matthew E. Marra
Senior Director, Environmental



/sjn
Attachments