625 N. French Dr., Hobbs, NM 88240 Energy Minerals <u>istrict III</u> Energy Minerals 000 Rio Brazos Road, Aztec, NM 87410 Oil Conser <u>istrict IV</u> 1220 South			New Mexico and Natural Resources vation Division St. Francis Dr. c, NM 87505			RECEIVED FEB 28 2012 Submit 1 Copy to appropriate accordance with NMOCD ARTESIA			
	Release Notific	atior			ction				
Name of Company: Enterprise	Field Services LLC /	10000	OPERA	TOR Jim Heap		🗌 Initia	al Report	\square	Final Re
Address: 1100 Louis	iana Street, Houston,			No.: 432-686-54	104				
77002 Facility Name: Pipeline Box Canyon Gathering System			Facility Type: Pipeline						
Surface Owner Mineral Owner			API No.						
	LOCA	TIO	N OF REI	LEASE					
Unit Letter Section Township Ra	inge Feet from the	North/	South Line	Feet from the	East/W	est Line	County		
14 218 2	21E							Eddy	
	Latitude: <u>N 32.4</u>	76018	Longitu	ide: <u>W 104.773</u>	<u>593</u>				
	NAT	URE	OF REL			** 1 -			
Type of Release: Natural Gas Source of Release:	Volume of Release: 819 Mcf Volume Recovered: 0 Date and Hour of Occurrence: Date and Hour of Discover								
Maintenance Blowdown			02/16/2012 1300 MST 02/16/201				2 13:00 (MST)		
Was Immediate Notice Given?	es 🗌 No 🗌 Not Re	quired	If YES, To Region 2 (Whom? CD by phone					
By Whom? Jim Heap			Date and Hour: 02/17/2012 09:30 (MST)						
Was a Watercourse Reached?	es 🖂 No		If YES, Volume Impacting the Watercourse.						
Describe Cause of Problem and Remedial <i>CAUSE:</i> Hydrate build-up caused an inc <i>ACTION:</i> The line was blocked-in and blocked-i	crease in line pressure.	e hydrat	es.						
Describe Area Affected and Cleanup Action All gas was lost to atmosphere.	on Taken.*								·
I hereby certify that the information given regulations all operators are required to rep public health or the environment. The acc should their operations have failed to adeq or the environment. In addition, NMOCD federal, state, or local laws and/or regulation	port and/or file certain re eptance of a C-141 repo uately investigate and re acceptance of a C-141 r	elease n rt by th emediat	otifications a e NMOCD m e contaminati	nd perform correct arked as "Final Re on that pose a three	tive acti- eport" de eat to gre	ons for releases not releases not releases out the second se	eases which ieve the ope r, surface wa	may en rator of iter, hui	danger liability nan healt
rederal, state, or local laws and/or regulation			Approved by Environmental Specialist:				N DIVISION pted for record NMOCD		
Signature:									
Signature:					44				
	ntal			AUG 0 8 20	13 ₁	Expiration	Date:		
Signature:	ntal		Approval Da		13 F	Expiration	Date: Attached		
Signature: Printed Name: Matthew E. Marra Title: Senior Director - Environmer			Approval Da		13 ₁	Expiration			



ENTERPRISE PRODUCTS PARTNERS L.P. ENTERPRISE PRODUCTS HOLDINGS LLC (General Partner) ENTERPRISE PRODUCTS OPERATING LLC

RECEIVED FEB 2 8 2012 NMOCD ARTESIA

February 21, 2012

7011 1570 0003 0830 3427 Return Receipt Requested

Mr. Mike Bratcher District Supervisor New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE: Form C-141 Report of Gas Loss, Box Canyon Gathering Line Enterprise Products LLC

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC, Enterprise Products LLC is submitting the required C-141 Form for an 819 MCF release from our Gathering Tie-in lines at Box Canyon 4 and Box Canyon 5 due to hydrate build-up in those lines. Verbal notification was made to your office on February 17, 2012.

If you have any questions or need additional information, please contact our area field representative, Jim Heap, at 432-696-5404 (jkheap@eprod.com) or me directly at 713-381-6684.

Yours truly,

Matthew E. Marra Sr. Director - Environmental

/sjn attachments

(2) A gradient of the second state of the second se Second secon second sec

P. O. BOX 4324 HOUSTON, TX 77210-4324 713.381.6500 1100 LOUISIANA STREET HOUSTON, TX 77002-5227 www.epplp.com