


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nJMW 1324640760*

**OPERATOR**  Initial Report  Final Report

Name of Company	Chevron USA Inc. <i>4323</i>	Contact	David A. Pagano
Address	15 Smith Rd., Midland, TX, 79705	Telephone No.	wk: 575-396-4414X275 cell: 505-787-9816
Facility Name	Skelly 907 BTY <i>5.28.13</i>	Facility Type	Oil Production Batteries
Surface Owner	Federal BLM	Mineral Owner	Federal
		API No.	

**SKU 907 BTY (CTB) - Latitude: 32.819634 / Longitude: -103.872881**

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	22	17S	31E					Eddy

**NATURE OF RELEASE**

Type of Release	Gases to a Flare	Volume of Release	1400 MSCF	Volume Recovered	0 MSCF
Source of Release	Flare	Date and Hour of Occurrence	05/28/13 11:00AM	Date and Hour of Discovery	05/28/13 11:00AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Frontier shut in sales line due to pipeline issues causing Chevron to curtail gas at the battery. Expect Frontier to be down for a few weeks to repair line.					
Describe Area Affected and Cleanup Action Taken.* Shut in wells to minimize flaring. Chevron will stay in close contact with frontier so we can stop flaring as soon as they are able to accept our gas in the sales line.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:	<i>David Pagano</i>				
Printed Name:	David A. Pagano	Approved by Environmental Specialist: Signed <b>NMOCD</b>			
Title:	Health & Environmental Specialist	Approval Date:	<b>SEP 03 2013</b>	Expiration Date:	
E-mail Address:	dpgn@chevron.com	Conditions of Approval:			Attached <input type="checkbox"/>
Date:	05/29/13	Phone:	505-787-9816		

\* Attach Additional Sheets If Necessary

*fJMW 1321131421*

*iJMW 1324641954*

*ZRP-1887*

**Bratcher, Mike, EMNRD**

---

**From:** Pagano, David (David.Pagano) <David.Pagano@chevron.com>  
**Sent:** Wednesday, May 29, 2013 3:09 PM  
**To:** Pagano, David (David.Pagano); Bratcher, Mike, EMNRD  
**Cc:** Moschetti, Nick (NMOS); DeLeon, Josepha  
**Subject:** Initial C141 & C-129 report for flaring at SKU 907 that started on 5/28/13 at 11AM  
**Attachments:** C-129 - Skelly 907 Battery S.pdf; 20130528 C-141 Skelly 907 Bty Flare IS.pdf

Mr. Bratcher,

Here is the initial C-141 & C-129 for the flaring at our SKU 907 Battery that started yesterday due to Frontier Shutting in our sales line due to pipeline issues they are having. We have shut in our gas wells to minimize flaring and we expect them to be down for a few weeks. Once we are back online I will send you the final report. Please let me know if you have any questions or need additional information.

Regards,

**David A. Pagano**

*MCA Health & Environmental Specialist (Oil Area – Vacuum/Buckeye, Dollarhide & Sundown)*

56 Texas Camp Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

[dpagn@chevron.com](mailto:dpagn@chevron.com)

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."